

NEW MEXICO OIL CONSERVATION COMMISSION
DRAWER DD
ARTESIA, NEW MEXICO

FIELD REPORT FOR CEMENTING OF WELLS

Operator <u>Tom Brewer Dry Co. Inc.</u>		Lease <u>West Antelope sink unit.</u>		Well # <u>1</u>	
Location of Well	Unit <u>19805-6600</u>	Section <u>35</u>	Township <u>19</u>	Range <u>23</u>	County
Drilling Contractor <u>Tom Brewer Dry Co.</u>		Type of Equipment <u>Rotary</u>			
<u>APPROVED CASING PROGRAM</u> <u>9200 Perm.</u> <u>Approved 2-10-64</u>					
Size of Hole <u>12 1/4" to 310</u>	Size of Casing	Weight Per Foot	New or Used	Depth	Sacks Cement
<u>12 1/4" + 11"</u>	<u>8 7/8</u>	<u>24</u>	<u>used</u>	<u>2000</u>	<u>Circulate</u>
<u>7 7/8</u>	<u>4 1/2</u>	<u>10.5 + 11.6</u>	<u>New</u>	<u>9200</u>	<u>300</u>
Casing Data: <u>34</u>					
Surface <u>34</u> joints of <u>9 5/8</u> inch <u>32 3/4</u> # Grade <u>H</u>					
(Approved) (Rejected)					
Inspected by <u>T. L. Starnett</u> date <u>2-21-64</u>					
Cementing Program					
Size of hole <u>11</u> Size of Casing <u>8 5/8</u> Sacks cement required					
Type of Shoe used <u>Guide</u> Float collar used <u>Halliburton</u> Btm 3 jts welded <u>& thread lock</u>					
TD of hole <u>1000</u> Set <u>988</u> Feet of <u>8 7/8</u> Inch <u>32 3/4</u> # Grade <u>H</u>					
New-used csg. @ <u>988</u> with <u>150</u> sacks neat cement around shoe					
+ <u>350</u> sack <u>1000</u> additives <u>4% gel 2% cacl 12 1/2 # gylomite per sack 1/4 lb salt per</u>					
Plug down @ <u>6</u> (PM) Date <u>2-25-64</u>					
Cement circulated <u>No</u> No. of Sacks					
Cemented by <u>Halliburton</u> Witnessed by <u>R. L. Starnett</u>					
Temp. Survey ran @ <u>12:01</u> (AM) Date <u>2-26-64</u> top cement @ <u>236</u>					
Casing test @ <u>5:30</u> (AM) Date <u>2-27-64</u>					
Method Used <u>sump</u> Witnessed by <u>R. L. Starnett</u>					
Checked for shut off @ <u>2:45</u> (PM) Date <u>2-27-64</u>					
Method used <u>dusting at 2200</u> Witnessed by <u>R. L. Starnett</u>					
Remarks:					
<u>TD 8829 R.H. 35 sacks @ 8829-8729 35 sacks @ 6600-6500</u>					
<u>35 sacks @ 5150-5050 35 sacks 3600-3500 50 sacks 10</u>					
<u>35 sacks 250 10 sacks @ surface 11:15 AM 3-9-64</u>					

2-21-64 attempted to run $8\frac{5}{8}$ stuck pipe
hole filled with gravel.

Dumped 175 sacks in hole when pipe free
reamed $12\frac{1}{4}$ hole to 1000 feet ran $9\frac{5}{8}$ to
988 feet 2-25-63 with basket at 6872718
Pumped in estimated 500-550 barrels of mud, 100 straight
The rest watered. Mud down at 6:00 PM. Did not
circulate.

and 112 sacks to 2-25-63