Monsanto

Monsanto Company Production Department 321 West Texas Midland, Texas 79701 Phone: (915) 683-3306

January 14, 1975

RECEIVED

JAN 1 6 1975

New Mexico Oil Conservation Commission P.O. Drawer DD Artesia, New Mexico 88210

O. C. C.

Attn: Mr. W. A. Gressett

RE: Miller Federal #1-6 Sec. 3-21-27 Dagger Draw #1-0 Sec. 6-20-25

Gentlemen:

Cert :

Monsanto respectfully requests that the subject wells be granted an exception to the annual packer leakage test due to the danger in shutting the wells in. The latest well tests and pressure are listed below:

Hiller	Federal	(Morrow): (Acoka).	2500 MCF Shut in,	40 BC 516P =	, FTP = 1000	= 700	
Dagger			470 MCF, Shut in;			FTP =	450

The Dagger Draw well will load up and die due to the water production. Offset wells to the Miller Federal in the Morrow have lost large portions of their productivity when shut in. Burton Flat No. 1 dropped from 6 MMCF to 2 MMCF after being shut in. Burton Flat No. 2 has also shown a decline in production after shut in.

Yours very truly,

M. Scholl

District Production Manager

EMS:SKL:mm