Form 3160-5 November 1983) Formerly 9-331) DEPA Bi	U TED STATES ARTMLINT OF THE INT UREAU OF LAND MANAGE	OIL CONS. COMVISSION SUBMIT IN TEL CATE CERIOR verse aide Sill, NM 88210 MENT	5. LEASE DESIGNATION AND SEEIAL NO. NM 2938	
	PROPOSAL TO AND REPOR		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
OIL [] GAS []			7. UNIT AGREEMENT NAME	
NAME OF OPERATOR	8 St.	·····	8. FARM OR LEASE NAME	
ARCO Oil and Gas Company - Division of Atlantic Richfield Com			Panco Federal	
ADDRESS OF OPERATOR	•	RECEIVED BY	9. WBLL NO.	
P.O. Box 1610, Midland, Texas 79702 LOCATION OF WELL (Report location clearly and in accordance with any State requirements) See also space 17 below.) At surface 1980 Field d 660 Field (the text) At surface 1980 Field d 660 Field (the text)			1	
See also space 17 below.) At surface 1980 FWL 4 660 FNL (Unit C)		FEB 12 1986	10. FIELD AND FOOL, OE WILDCAT Shugart - Queen	
		O. C. D.	11. SHC., T., B., M., OB BLK. AND SURVEY OR AREA	
		ARTESIA, OFFICE	23-18S-31E	
. PERMIT NO.	15. ELEVATIONS (Show whet		12. COUNTY OF PARISH 13. STATE	
API #30-015-10356	GR 3693		Eddy N. M.	
		aie Nature of Notice, Report, or C		
	CK PAPPIOPIIGIE DOX 10 INGICC			
TEST WATER SHUT-OFF	[]		IBNT REPORT OF:	
FRACTURE TREAT	PULL OR ALTER CASING	WATER SHUT-OFF FRACTURE TREATMENT	ALTERING CASING	
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDON MENT*	
REPAIR WELL	CHANGE PLANS	(Other)	of multiple completion on Well	
2. <u>100 sx</u> 1730-1830 3. <u>*</u> 0-650.Per	ollows: 6.CR @ 3375.450'C D.Perf @ 1830.CR @ M rfs @ 650. In & behi rmined by pump-in dat	nd 4-1/2" csg.		

*See Instructions on Reverse Side



ARCO Oil & Gas Company Division of Atlantic Richfield Company

Blow Out Preventer Program

Lesso Name Panco Federal

Well No. /

Location 1980 FWL + 660 FNL (Unit C) 23-185-31E + Eddy (0., N.M.

BOP to be tested when installed on well and will be maintained in good working condition during drilling. All wellhead fittings to be of sufficient pressure to operate in a safe manner.