

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN THIS MANNER
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

100 54700

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Simon "A"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Lusk Strawn

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 13, T19S, R31E

12. COUNTY OR PARISH

EDDY

13. STATE

N. Mex.

1. OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR

Phillips Petroleum Company

3. ADDRESS OF OPERATOR

Room B-2, Phillips Bldg., Odessa, Texas

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface

SW/4 SE/4, 660' FS, 1980' FW lines, Section 13

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3556' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO :

SUBSEQUENT REPORT OF :

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other) _____

(Other) _____

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

On 9-21-66, moved in and rigged up service unit; pulled tubing. Halliburton treated Strawn perforations 11418-34' with 10,000 gals retarded (CRA) acid in 3 stages: 100 bbls lease oil and 2000 gals acid; 50 bbls lease oil and 2000 gals acid; 50 bbls lease oil and 6000 gals acid. With 172 bbls in formation pressure breaks from 4500# to 1800#. Increased injection rate to 10 BPM, pressure increased to 4500#. Average injection rate 1.5 BPM. Maximum pressure 4500#, minimum 1800#, instant shut down pressure 4200#. Set tubing at 11513'. Tested well on 9-30-66, well flowed 2 1/2 hrs, 28/64" choke, FTP 190#, no water, 397 BO, 527 maf gas, GOR 1328, oil gravity 47.3.

RECEIVED

OCT 1 0 1966

D. C. C.
ARTESIA, OFFICE

18. I hereby certify that the foregoing is true and correct

SIGNED

H. J. Mueller
H. J. Mueller

TITLE **Associate Reservoir Engineer**

DATE

10-7-66

(This space for Federal or State office use)

APPROVED BY _____

TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY:

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.