

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIP
(Other instruction
verse side)Form approved.
Budget Bureau No. 42-11424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back a well and reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	DEC 13 1971	5. LEASE DESIGNATION AND SERIAL NO.	5. NM 1107697
2. NAME OF OPERATOR	Deneco Oil Company	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR	Box 1031 - Midland, Texas 79701	7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface	1980' FNL + 640' FEL of Section 23	8. FARM OR LEASE NAME	Don E. Federal
14. PERMIT NO.		9. WELL NO.	1
15. ELEVATIONS (Show whether DF, RT, CR, etc.)	3532.5' GR	10. FIELD AND POOL, OR WILDCAT	Lusk & Strawn
		11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA	23 - 19S - 31E
		12. COUNTY OR PARISH	Eddy
		13. STATE	New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☒	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	
(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)			

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Set CIBP @ 11,240' in 4 1/2" casing + cap w/35' cement. Shoot 4 1/2" casing @ free point (TR @ 10,140').
Spot plugs - 30 sy @ 4 1/2" casing stub through casing.
30 sy 8440' - 8340'
30 sy 7070' - 6970'
30 sy 5390' - 5290'
35 sy 3935' - 3835'
Shoot 8 3/8" casing at free point (TR @ 2160')
Spot plugs - 50 sy to be 50' in + 50' out of 8 3/8" casing stub through casing.
75 sy across 13 3/8" casing shoe (700' - 600')
10 sy @ surface - install dry hole marker.

Propose to begin 12-16-71

RECEIVED

DEC 10 1971

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Maris L. Cannon

TITLE

Clerk

DATE

12-9-71

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

12-9-71

APPROVED
DEC 10 1971
R. L. BECKMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side