

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRI
(Other instruction
verse side)ATE*
reForm approved.
Budget Bureau No. 42-B1424.
5. LEASE DESIGNATION AND SERIAL NO.

NM 0107697

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Jones Federal "E"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Lusk - Strawn

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 23, T19S, R31E

12. COUNTY OR PARISH 13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ P&A

2. NAME OF OPERATOR
Tenneco Oil Company

3. ADDRESS OF OPERATOR
Suite 1200 - Lincoln Tower Bldg. - Denver, Colo.

4. LOCATION OF WELL (Report location clearly and in accordance with each State requirements.
See also space 17 below.)
At surface
1980' F/NL and 660' F/EL

14. PERMIT NO.

15. ELEVATION (Show whether DF, RT, GR, etc.)
3545 DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	☐	PULL OR REPAIR CASING	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETION	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐
REPAIR WELL	☐	CHANGE PLANT	☐
(Other)			

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☒
(Other)			

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS clearly and in pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directional drilled, give surface location and measured and true vertical depths for all markers and zones pertinent to this work.*

Well plugged and abandoned as follows:
Shot and pulled 4 1/2" casing from 1078', and pulled 5887' of 2-3/8" tubing. Set 11,240 capped W/35 cement. Cement plugs installed as follows:

DEPTH

From	To	No. Sacks
7354	7254	30 across 4 1/2 csq. stub
7070	6970	
5390	5290	
3935	3835	
1128	1028	35 across 8-5/8 csq. shoe
703	603	50 in & out of 8 5/8 csq stub.
Surface		75 across 13 3/8" csq. shoe
		10

Installed dry hole marker and obtained location

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Production Clerk

DATE 8-15-72

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL IF ANY:

TITLE

DATE

See instructions on Reverse Side