RECEIVED

DEC 1 1 1964

O. C. C.

(1), CO

DRILLING PROGNOSIS Sweeney Federal No. 1 Page Three

DRILLING TIME:

1. A recorder with torque, hook load and rate of penstration will be used. 2. Record 10' drilling times from surface to T.D. on company forms.

DRILL PIPE MEASUREMENTS: Strap drill pipe at all casing, testing, coring, logging, points and at T.D.

DRILLING SAMPLES:

- 1. Two sets of 10' samples will be caught, washed, sacked, and labeled in bundles of 100' from surface to T.D.
- 2. Circulating and additional samples will be obtained as directed.
- 3. Quart samples will be obtained of all fluids recovered on DST.

CORES: Mone anticipated.

DRILL STEM TESTING: Tests to be taken at direction of vellsite geologist.

LOGGING:

- 1. Gamma Pay-Sonic Caliper from T.D. to base of intermediate casing.
- 2. Dual induction-latering through sections as specified by wellsite geologist.

BLOW-OUT PREVENTORS:

- 1. Series 900 or better, double ram with manual and remote control proventors shall be used from base of surface to T.D.
- 2. BOP shall be checked daily and reported on drilling report.
- 3. A rotating drilling head shall be used during any air or gas drilling.

DAILY DRILLING REPORTS:

- 1. The AAODC report will be used.
- 2. This report will be filled out in detail and mailed to Midland District Office four times per week.
- 3. Morning reports shall be made to the Midland District Office each week-day morning between 8:00 a.m. and 8:30 a.m., CSN.
- 4. The company forms for daily drilling report and daily cost report will be prepared each day and delivered to the drilling section at the end of each well.

DEVIATION:

- 1. Deviation in the surface hole shall not exceed 1°.
- 2. Deviation surveys shall be taken on every trip or every 500', whichever is first.