

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	3

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-100
Supersedes G11
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
E-1001

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Sunray DX Oil Company	8. Farm or Lease Name N.M. State "Y"
3. Address of Operator P.O. Box 128, Hobbs, New Mexico	9. Well No. 4
4. Location of Well UNIT M 990 FEET FROM THE South LINE AND 990 FEET FROM West LINE, SECTION 32 TOWNSHIP 18 RANGE 31 NMPM.	10. Field and Pool, or Wildcat Shugart (Y. SR. Q.G)
15. Elevation (Show whether DF, RT, GR, etc.) 3557.5 GR	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
WELL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spud 10" hole at 1:45 P.M. 2-26-65.
2. Drilled to TD 872'. Ran 27 jts 8 5/8", 24#, J-55 Csg to Csg Point 872'. Cntd w/350 sx Incore Pos w/12.5# Gilsonite per sx plus 75 sx Incore Pos Neat.
3. WOC 18 hrs, nipple up & drill to 877'. Bailed dry and test for 1 hour. Tested dry. Now drilling ahead.

RECEIVED

MAR 15 1965

O. C. C.
ARTEZIA, OFFICE

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B.F. Brawley TITLE District Engineer DATE March 12, 1965

APPROVED BY M.L. Armstrong TITLE OIL AND GAS INSPECTOR DATE MAR 15 1965

CONDITIONS OF APPROVAL, IF ANY: