

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Southland Royalty Company

3. Address and Telephone No.

P.O. Box 51810, Modland, TX 79710-1810

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

990' FNL & 1980' FWL
Sec. 27, T18S, R31E

5. Lease Designation and Serial No.
71-029392B

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Hinkle F #3

9. API Well No.

30-015-10592

10. Field and Pool, or Exploratory Area

Shugart (Y, 7R, QN, GB)

11. County or Parish, State

Eddy

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12/9/92 MIRU. install BOP. PU bit & scraper. RIH w/tbg. tagged 3815'. POOH. LD bit/scraper. PU pkr & RBP. RIH to 3496' spt RBP. PU 3460' set pkr. test RBP. Rls pkr. PU to 2526'. load csg. test csg. moved pkr to 3460' & tested. SDFN.
12/10-92 Retrieve RBP. POH w/RBP & pkr SD.
12/11/92 RIH w/cmt renr. set 3518'. PU spot 60sx, sting back into retainer. Spotted 60 sxs on top of retainer. POOH w/tbg. RIH to 2950' circ. POH. LD jts. Dug out cello. SD
12/12/92 RIH w/csg. cutter. cut @2010'. RIH w/csg. spear. RIH - perf sqz 2000'. RIH w/cmt retainer 1936'. pmped 150 sxs. POH w/tbg. SD.
12/13/92 RIH w/csg. gun to 390' sqz hles. PU cmt retainer set @870'. coat w/60 sxs PO of retainer. 10 sxs on top. POOH LD WS. RIH w/ csg. gun shoot @55' sqz. holes. circ. 35 sxs to surface. RDMO. Cut off WH.

Approved as to accuracy of the information here.
Liability under bond is reduced until
surface restoration is completed.

Post ID
1-22-93
P-A

14. I hereby certify that the foregoing is true and correct

Signed

Title Production Assistant

Date 1-6-93

(This space for Federal or State office use)

Approved by

Title

Date 1-19-93

Conditions of approval, if any: