

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

RECEIVED

APR 11 1991

O.C.D.

APPROVED

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Meridian Oil Inc. Southland Royalty

3. Address and Telephone No.

P.O. Box 51810, Midland, TX 79710 915-688-6800

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

990' FNL & 990' FWL
Unit D, Sec. 27, T18S, R31E

5. Lease Designation and Serial No.

LC

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Hinkle F #5

9. API Well No.

10. Field and Pool, or Exploratory Area

Shugart (Y,7R,QN,GB)

11. County or Parish, State

Eddy

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other add pay w/in same field

☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12/4/92 RU. TOH w/rods & pmp. TOH w/tbg. left mud anchor in hole. TIH w/bit & scraper on w.s. tag @3879.

12/5/92 Cir. @3879. TOH TIN w/o.s., B.S., & D.C. on W.S. Tag fish. TOH D.S. empty. TIN w/same try to cir. no show.

12/6/92 TOH. TIN w/ wash pips & DC on W.S. wash under fish. TOH. TIN w/B.S. & D.C. on W.S. caught fish @ 3879. TOH LID N.A.

12/7/92 RU. RIH w/csg. guns. 2 spf. perf. 3830-70 (82 holes) RD. Pupkr. set and test annulus, rls pkr. PU 9 its LD 3705'. set pkr. test annulus. rls pkr. POOH w/tbg. to 3415. SDFN

12/11/92 More pkr to 3904'. RU spot 200 qds of HeFe-HCL. pupkr 3700'. set pkr. brkdn perfs 2 drms SP358 25% mix 330 gls of 2% KEL. Trip thru perfs w/pkr. reset pkr. @3700'. frac. well. SIFN.

12/12/92 Open to tanks- bled wond, rls pkr. POH. PU collar. RIH. Tag 3880' cleaned out to 3915' POH. LD/WS. SIFN.

14. I hereby certify that the foregoing is true and correct

Signed

[Signature]

Title

Production Assistant

Date

1-6-93

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any: