Form 3160-5 June 1990)	UNITED STATES		FORM APPROVED Budget Bureau No. 1004–0135	
June 1990)		T OF THE INTERIOR LAND MANAGEMENT	Expires: March 31, 1993 5. Lease Designation and Serial No.	
			LC-029392(b)	
Do not u	se this form for proposals to dri	AND REPORTS ON WELLS ill or to deepen or reentry to a different reservoir R PERMIT—" for such proposals	<ol> <li>If Indian, Allottee or Tribe Name</li> </ol>	
		IN TRIPLICATE	7. If Unit or CA, Agreement Designation	
1. Type of Weil RECEIVED			8. Well Name and No.	
2. Name of Operator			Hinkle F #6	
4eria	tian Oll Inc. Sout	hland Royadty	9. API Well No.	
	d Telephone No. . Box 51810, Midland, TX	79710	10. Field and Pool, or Exploratory Area	
4 Location of Well (Footage, Sec., T., R., M., or Survey Description)			Shugart(Y,7R,QN,GB)	
2310' 27-18:	FSL & 1650' FWL S-31E		11. County or Parish. State Eddy	
12	CHECK APPROPRIATE BOX	s) TO INDICATE NATURE OF NOTICE, REPO	ORT, OR OTHER DATA	
TYPE OF SUBMISSION		TYPE OF ACTIO	N	
	Notice of Intent		Change of Plans	
	(TT)		New Construction	
X Subsequent Report			Non-Routine Fracturing Water Shut-Off	
	Final Abandonment Notice	Casing Repair Altering Casing Other add pay w/in same fi	Conversion to Injection	
. <u>,</u>			Completion or Recompletion Report and Log form.)	
13. Describe P give s 12/3/92	ubsurface locations and measured and true vertice	ll pertinent details, and give pertinent dates, including estimated date of star cal depths for all markers and zones pertinent to this work.)* g. swab tbg.down. TOH w/tbg. TIH w/h		
12/4/92	TIH w/bit & csg scraper C.O. to top of fish. 39	& csg scraper, 3886. test csg for leak. TOH chg out nipple. TIH w/bit & scra op of fish. 3912.		
12/5/92	TOH w/bit. TIH w/bumper sub & D.C. on W.S. wash 3912-42. plugged tbg. TOH w/fish LD wash pips w/tbg inside. TIH w/bit & D.C. on W.S. SDFN.			
12/6/92	6/92 TOH w/bit perf Loco Hills 3918-46'. 2 spf (58 holes), TIH w/pkr on W.S. 3946. Spot 20 gals 7½% NEFE NCL. Moved pkr 3840'. Move pkr 3774'. test tbg. TOH.			
12/7/92	TIH w/pkr on W.S. 3708'. move pkr to 3487' (above Penrose perfs 3542-52'). Pump 110 gals. SP 358 mix 8 bbls 2% KCL. followed up w/1000 gals $7\frac{1}{2}$ % NEFE. Flow back acid SD.			
12/8/92	TOH W.S. TIH w/tbg.	TIH wi/tbg. plunger & rods. Spcae o	ut. RDNO.	
14. I hereby certify that the foregoing is true and correct Production Assistant			1-6-92	
Signed _	m for Endersl or State office use)	Title	Date	
	ce for Federal or State office use)	Title	Date	
Approved by Little Little Little				
	C. Service 1001 method is a string for any	n knowingly and willfully to make to any department or agency of the Ur	ited States any false, fictitious or fraudulent statements	
or representat	C. Section 1001, makes it a crime for any personions as to any matter within its jurisdiction.		-	

ton Instruction on Devene Cid