

February 14, 1967

Southwestern Natural Gas, Inc.
412 First State Bank Building
Midland, Texas

Re: Dozier Federal Com No. 1 K,
14-19-31, Lusk-Strawn Pool,
Eddy County, New Mexico

Gentlemen:

A field inspection of the subject well was made February 13, 1967. Said inspection revealed a volume of gas being vented to the air, even though the well is connected to Phillips gas gathering system. A check at the Phillips booster station failed to turn up any cause for the forementioned venting.

Please examine this matter and advise this office, by return mail, as to the cause.

Very truly yours,

OIL CONSERVATION COMMISSION

R. L. Stamets
Geologist

RLS/bh

