

SOUTHWESTERN NATURAL GAS, INC.  
412 FIRST STATE BANK BUILDING  
MIDLAND, TEXAS 79701  
MU 2-7161

W. W. BUCHANAN, PRESIDENT  
1109 N. B. C. BUILDING  
SAN ANTONIO, TEXAS

L. N. DUNNAVANT  
VICE PRESIDENT AND  
OPERATIONS MANAGER

February 16, 1967

RECEIVED

FEB 17 1967

ART. REG. OFFICE

Oil Conservation Commission  
P. O. Drawer DD  
Artesia, New Mexico

Attention R. L. Staments, Geologist

Re: Dozier Federal Comm No. 1-K,  
14-19-31, Lusk-Strawn Pool,  
Eddy County, New Mexico

Gentlemen:

We acknowledge receipt of your letter dated February 14, asking why gas was being vented to the air on subject well. This was due to excessive line pressure on Phillips Petroleum Company's gathering line causing a small volume to vent at the separator. The condition has been remedied.

Very truly yours,

SOUTHWESTERN NATURAL GAS, INC.

L. N. Dunnavant  
Vice President

LND/eb