

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/-
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>State OG-16</b>
7. Unit Agreement Name
8. Farm or Lease Name <b>State OG-16</b>
9. Well No. <b>1</b>
10. Field and Pool, or Wildcat <b>Turkey Track</b>
12. County <b>Eddy</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Dry Hole</b>
2. Name of Operator <b>Western Oil Fields, Inc.</b>
3. Address of Operator <b>P.O. Box 1137, Hobbs, New Mexico 88240</b>
4. Location of Well UNIT LETTER <b>K</b> , <b>1650</b> FEET FROM THE <b>South</b> LINE AND <b>1650</b> FEET FROM THE <b>West</b> LINE, SECTION <b>10</b> TOWNSHIP <b>19S</b> RANGE <b>29E</b> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**It is our intention to plug and abandon this well in the following manner:**

**25 sack plug at 2185' - above perforation**  
**25 sack plug at top of casing cutoff**  
**25 sack plug at bottom of surface pipe (368')**  
**10 sack plug in top of surface with 4" X 5' marker**

**RECEIVED**

**DEC 2 1966**

**ATTENTION OFFICE**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *[Signature]* TITLE **Production Clerk** DATE **Dec. 20, 1966**

APPROVED BY *[Signature]* TITLE **OIL AND GAS INSPECTOR** DATE **DEC 23 1966**

CONDITIONS OF APPROVAL, IF ANY: *Intervals between plugs filled with mud*  
*25 sack plug at th. base of th. L.O.*