

N. M. O. G. SURVEY  
**UNITED STATES**  
**DEPART. NT OF THE INTERIOR**  
**GEOLOGICAL SURVEY**

SUBMIT IN TRIPLICATE  
(Other instruct  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

<p>1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER</p> <p>2. NAME OF OPERATOR C. W. Trainer</p> <p>3. ADDRESS OF OPERATOR P. O. Box 1100, Hobbs, New Mexico</p> <p>4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface  660' FSL &amp; 1980' FWL, Sec. 1-19S-31E</p>		<p>5. LEASE DESIGNATION AND SERIAL NO. LC064577-B</p> <p>6. IF INDIAN, ALLOTTEE OR TRIBE NAME</p> <p>7. UNIT AGREEMENT NAME</p> <p>8. FARM OR LEASE NAME Joyce A. Cam</p> <p>9. WELL NO. 1</p> <p>10. FIELD AND POOL, OR WILDCAT Lusk Strawn</p> <p>11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA Sec. 1-19S-31E</p> <p>12. COUNTY OR PARISH Eddy County</p> <p>13. STATE New Mexico</p>
<p>14. PERMIT NO.</p>	<p>15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3621.6 GL</p>	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input checked="" type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)	<input type="checkbox"/>	(Other)	<input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

TD 387' with cable tools.  
Plan to plug and abandon by filling hole with heavy mud and cementing regulation  
4" marker from 20' to 4' above G.L.  
Will clean up surface location.

**RECEIVED**

MAR 1 1967

U. S. G.  
GEOLOGICAL SURVEY


**RECEIVED**  
MAR 29 1967  
U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED C. W. Trainer TITLE Owner-Operator DATE 3-28-67

(This space for Federal or State office use)

APPROVED BY R. L. BECKMAN TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:



\*See Instructions on Reverse Side