

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Gulf Oil Corporation		8. FARM OR LEASE NAME Holder "CT" Federal	
3. ADDRESS OF OPERATOR Box 670, Hobbs, New Mexico 88240		9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FN & WL, Section 11, 19-S, 31-E		10. FIELD AND POOL, OR WILDCAT under Inack Stream	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3589' OL	
		12. COUNTY OR PARISH Eddy	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

11,310' TD, 11,273' FB.

Sharp Drilling Company reached TD of 7-7/8" hole at 11,310' at 5:30 AM, May 23, 1967. Circulated and ran logs. Ran 55 joints, 1792' of 5 1/2" 17# N-80 LT&C, 43 joints, 1442' of 17# J-55 ST&C, 151 joints, 4877' of 15.50# J-55 ST&C, 1 joint, 32' of 15.50# J-55 ST & buttress coupling and 96 joints and 1 cut joint, 3184' of 15.50# J-55 Buttress. Total of 346 joints and 1 cut joint, 11,297'. Set and cemented at 11,310' with 180 sacks of Class C cement with 16% gel and .3% CRR-2, mixed with 2% pre-dissolved salt and 200 sacks of Class H cement with 1.5% CFR-2. WOC 8 hours. TS indicated TOC at 8720'. WOC over 24 hours. Tested casing with 1000#, 30 minutes. OK.

RECEIVED

JUN 7 1967

O. C. C.
AREA, OFFICERECEIVED
JUN - 5 1967
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

ORIGINAL SIGNED BY
SIGNED **C. D. BORLAND**TITLE **Area Production Manager**DATE **May 31, 1967**

(This space for Federal or State office use)

APPROVED BY **[Signature]**
CONDITIONS OF APPROVAL, IF ANY:TITLE **DISTRICT ENGINEER**DATE **JUN 1**

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; and or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.