

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYIN. M. O. C. C. COPY
SUBMIT IN (Other than duplicate)
75 on reForm approved.
Budget Bureau No. 42-71424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

N14039879

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Road 11 Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Lusk Strawn

11. SEC., T., E., M., OR BLK. AND
SURVEY OR AREA

Sec 11 T-19S R 31E

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

1. OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

Continental Oil Company

3. ADDRESS OF OPERATOR

P. O. Box 460 Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)

At surface

660' FSL + 1980' FEL, Section 11, T-19S,
R-31E, Eddy Co., New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3577 DF

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

① Cut and pulled 11068' - 2" thg. ② Set 50 sk.
Cmt. plug @ 11063' * ③ Shot 4 1/2" csg. @ 9961 and pulled
same ④ Set 25 sk. cmt. plug @ 9961' ⑤ Set 25 sk. cmt.
plug @ 7300' - 7360' ⑥ Set 25 sk. cmt. plug from 4000'
- 3900' ⑦ Pulled 2164' - 7 5/8" csg. ⑧ Set 25 sk. cmt.
plug @ 2187' ⑨ Set 25 sk. cmt. plug @ 693' (bottom of
surface csg.) ⑩ Set 10 sk. cmt. surface plug
⑪ Created dry hole marker and restored location
to original condition

* verbal approval given by Jim Knapp to J. F. Bates

18. I hereby certify that the foregoing is true and correct

SIGNED

M. E. Yeakley

TITLE Adm. Section Chief

DATE 2-4-69

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY

TITLE

APPROVED
MAY 22 1969
R. L. BEEKMA

*See Instructions on Reverse Side

RECEIVED
FEB-5 1969
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO
RECEIVED
MAY 23 1969
D. C. C.
ARTESIA, OFFICE