July 1989) Formerly 9–331)	UNI DEPARTMENT	D STATES F OF THE INTERIOR	OONTACT RECEIVING OFFICE FOR NMP OF COPIES RECUIN (Other Instructions on reverse side)	MM Roswell Dist Modified Form No <u>NMO60-3160-4</u> 5. LEASE DESIGNATION	. C	
	BUREAU OF	LAND MANAGEMENT	RECEIVE	- ¹ NM 14118		
	s form for proposals to	AND REPORTS ON drill or to deepen or plug back to FOR PERMIT for such propose	o a different reservoir.	6. IF INDIAN, ALLOTTEE	OR TRIBE NAME	
I. OIL GAN WELL OTHER Recompletion 2. NAME OF OPERATOR			RECEIVED	N/A	7. UNIT AGREEMENT NAME N/A 8. FARM OR LEASE NAME	
YATES PETROLEUM CORPORATION			505/748-246A		Allison CQ Federal	
ADDRESS OF OPERATO	DB		150 CO 30	9. WELL NO.		
105 South 4th St., Artesia, NM 88210 4. LOCATION OF WELL (Report location clearly and in accordance with any State			requiremente. • C. D.	10. FIELD AND POOL, OR WILDCAT		
See also space 17 below.) At surface			ARTESIA, OFFICE	Undesignated Canyon 11. SBC, T., R., M., OR BLK, AND SURVEY OR AREA Unit P -		
660' FSL & 660' FEL, Sec. 22-19S-24E						
4. PERMIT NO.	15.	ELEVATIONS (Show whether DF, RT, G	ir, etc.)	Sec. 22-T19S-R 12. COUNTY OR PARISH	24E, NMPM 13. ETATE	
API #30-015-20	278	3659' GR		Eddy	NM	
6.	Check Appropri	ate Box To Indicate Natur	e of Notice, Report, or	Other Data		
	NOTICE OF INTENTION TO): -	SUBSEC	QUENT REPORT OF :		
TEST WATER SHUT- Phacture treat	MULTIPI	ALTER CASING	WATER SHUT-OFF FRACTURE TREATMENT	BEPAIRING W ALTERING CA	SING	
SHOOT OR ACIDIZE Repair well	ABANDO: CHANGE		Other) Perforate	X j ABANDONMEN , Treat	т• Х	
(Other)	1		(NOTE : Report result Completion or Recom	is of multiple completion of pletion Report and Log for	n Well m.)	
v/770 sx Premiand cement. Po	um cement. Stu erforated 7440-	eze holes 8106' and ing out of retainer. 7684' w/32 .41" hole d perfs w/3500 gals	Pulled tubing to es as follows: 74	o 5000'. Drille 440-47, 7471-75, Swabbed and test	d retainer 7586-91,	
2-12-89 - 1-6 set 7631' and p sealers. Swab set 7575' and p Perforated 7490 37, 41 and 7541 7500'. Reperfo 7440-7611' w/21	packer set 7507 bed well - gas packer set 7520 0-7545' w/ll - 5'. Acidized p orated 7440-761 5000 gals 20% N	rforated 7559-63 and TSTM. TOH w/packer Swabbed w/small .50" holes as follow erfs w/350 gals acid 1' w/2 JSPF. WIH and EFE acid and 4 drops oun. Rigged down unit	d 7607-11'w/10 - w/2500 gals 15% N and RBP. TIH w/s show of oil. Ga ws: 7490, 92, 98 d. Acid communic nd set packer @ 7 s of block. Swab	EFE with 50# blo new RBP and pack s TSTM. , 7500, 15, 18, ated up thru per 352'. Acidized bed well. Small RBP set @ 7640	F). RBP ck and bal er. RBP 20, 22, fs 7490- perfs show oil.	
12-12-89 - 1-6 set 7631' and p sealers. Swab set 7575' and p Perforated 7490 37, 41 and 754 7500'. Reperfo 7440-7611' w/2 Show of gas af	packer set 7507 bed well - gas packer set 7520 0-7545' w/ll - 5'. Acidized p orated 7440-761 5000 gals 20% N ter each swab r	rforated 7559-63 and TSTM. TOH w/packer Swabbed w/small .50" holes as follow perfs w/350 gals acid 1' w/2 JSPF. WIH and EFE acid and 4 drops run. Rigged down units ACC	d 7607-11'w/10 - w/2500 gals 15% N and RBP. TIH w/s show of oil. Ga ws: 7490, 92, 98 d. Acid communic nd set packer @ 7 s of block. Swab it 1-6-90. Note:	EFE with 50# blo new RBP and pack s TSTM. , 7500, 15, 18, ated up thru per 352'. Acidized bed well. Small RBP set @ 7640	F). RBP ck and ball er. RBP 20, 22, fs 7490- perfs show oil.	
12-12-89 - 1-6 set 7631' and p sealers. Swable set 7575' and p Perforated 7490 37, 41 and 7542 7500'. Reperfor 7440-7611' w/22 Show of gas after 8. I hereby certify that SIGNED	packer set 7507 bed well - gas packer set 7520 0-7545' w/ll - 5'. Acidized p orated 7440-761 5000 gals 20% N ter each swab r	rforated 7559-63 and TSTM. TOH w/packer Swabbed w/small .50" holes as follow oerfs w/350 gals acid 1' w/2 JSPF. WIH and EFE acid and 4 drope bun. Rigged down unit Common Common acid	d 7607-11'w/10 - w/2500 gals 15% N and RBP. TIH w/s show of oil. Gas ws: 7490, 92, 98 d. Acid communic. nd set packer @ 7 s of block. Swab it 1-6-90. Note:	EFE with 50# blo new RBP and pack s TSTM. , 7500, 15, 18, ated up thru per 352'. Acidized bed well. Small RBP set @ 7640	F). RBP ck and ball er. RBP 20, 22, fs 7490- perfs show oil. '.	
12-12-89 - 1-6 set 7631' and p sealers. Swable set 7575' and p Perforated 7490 37, 41 and 7542 7500'. Reperfor 7440-7611' w/22 Show of gas after 8. I hereby certify that SIGNED	packer set 7507 bed well - gas packer set 7520 0-7545' w/ll - 5'. Acidized p orated 7440-761 5000 gals 20% N ter each swab r	rforated 7559-63 and TSTM. TOH w/packer Swabbed w/small .50" holes as follow oerfs w/350 gals acid 1' w/2 JSPF. WIH and EFE acid and 4 drope bun. Rigged down unit Common Common acid	d 7607-11'w/10 - w/2500 gals 15% N and RBP. TIH w/s show of oil. Gas ws: 7490, 92, 98 d. Acid communic. nd set packer @ 7 s of block. Swab it 1-6-90. Note: Acc FEB 2 3 1925	EFE with 50# blo new RBP and pack s TSTM. , 7500, 15, 18, ated up thru per 352'. Acidized bed well. Small RBP set @ 7640	F). RBP ck and ball er. RBP 20, 22, fs 7490- perfs show oil. '.	
 12-12-89 - 1-6- set 7631' and performed and performed 7490 37, 41 and 7541 7500'. Reperformed 740-7611' w/21 Show of gas af the space for peder of the space for peder for ped	packer set 7507 bed well - gas packer set 7520 0-7545' w/ll - 5'. Acidized p orated 7440-761 5000 gals 20% N ter each swab r	rforated 7559-63 and TSTM. TOH w/packer Swabbed w/small .50" holes as follow oerfs w/350 gals acid 1' w/2 JSPF. WIH and EFE acid and 4 drope bun. Rigged down unit Common Common acid	d 7607-11'w/10 - w/2500 gals 15% N and RBP. TIH w/s show of oil. Gas ws: 7490, 92, 98 d. Acid communic. nd set packer @ 7 s of block. Swab it 1-6-90. Note: Acc FEB 2 3 1925	EFE with 50# blo new RBP and pack s TSTM. , 7500, 15, 18, ated up thru per 352'. Acidized bed well. Small RBP set @ 7640	F). RBP ck and ball er. RBP 20, 22, fs 7490- perfs show oil. '.	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any files distillant or fraudulant states and for the states and files and files distillant or fraudulant states and for the states and files a