

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TR. CATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-01108

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Littlefield #13 Federal

9. WELL NO.

10

10. FIELD AND POOL, OR WELDEAT

Shugart (T. SR. G. Gbr.)

11. SEC., T., R. N. OR B&C. AND
SURVEY OR AREA

Section 22, 18-S, 31-E

12. COUNTY OR PARISH 13. STATE

Eddy

New Mexico

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐2. NAME OF OPERATOR
Gulf Oil Corporation3. ADDRESS OF OPERATOR
Box 670, Hobbs, New Mexico 882404. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FNL & 1980' FEL, Section 22, 18-S, 31-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3661' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

3450' TD, 3410' PB.

Perforated 5-1/2" casing with 2, 1/2" JHFF at 3336-40' and 3364-70'. Spotted 250 gallons of 15% NE acid over perforations. Frac treated with 35 barrels of gel water and 100 barrels of gel water containing 3% SFO. Flushed with 78 barrels of gel water. Maximum pressure 2050#, minimum 1700#, ISIP 1650#, AIR 27.6 bpm. Ran tubing and circulated hole clean. Set tubing at 3401'. Swabbed and cleaned up. Ran rods and pump and placed well on production.

18. I hereby certify that the foregoing is true and correct

ORIGINAL SIGNED BY

SIGNED C. D. BORLAND

TITLE Area Production Manager

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL IF ANY:

TITLE

DATE May 5, 1970

ACCEPTED FOR RECORD PURPOSES

MAY 7 - 1970
Date

ACTING District Engineer

*See Instructions on Reverse Side

RECEIVED
MAY 7 - 1970
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICORECEIVED
MAY 8 1970
ARTESIA, NEW MEXICO

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or Regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations to be detailed for Indian lands should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data pertaining to former or present productive zones, or other zones with present significant fluid content, not sealed off by cement or otherwise; depths (top and bottom), and method of placement of cement plugs; mud or other material placed below, between, and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth, by top of any left in the hole; method of closing top of well, and date well was conditioned for final inspection, looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1964 O-685229

RECEIVED
MAY - 1970
U.S. DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

*See Instructions on Reverse Side

ACTING District Engineer
MAY 7 - 1970
Date

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
SUNDRY NOTICES AND REPORTS ON WELLS

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

1. Abandonment	2. Completion	3. Drilling	4. Logging	5. Production	6. Testing	7. Other
----------------	---------------	-------------	------------	---------------	------------	----------

NOTE: Report results of operations, including description of work done, and results of tests, in the space provided below. Attach separate sheets if necessary. Indicate the date of completion of operations, and the date of the report.

NAME OF OPERATOR: _____

WELL NO.: _____

LOCALITY: _____

STATE: _____

DATE: _____