

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TR. DATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-014109

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Littlefield "AB" Federal

9. WELL NO.

11

10. FIELD AND POOL, OR WILDCAT

Shugart (Y. SR. G. Cbr.)

11. SEC., T., R., S., OR B.L. AND
SURVEY OR AREA

Section 22, 18-S, 31-E

12. COUNTY OR PARISH 13. STATE

Eddy

New Mexico

1. OIL ☒ GAS ☐ OTHER ☐
WELL WELL2. NAME OF OPERATOR
Gulf Oil Corporation3. ADDRESS OF OPERATOR
Box 670, Hobbs, New Mexico 882404. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FN & EL, Section 22, 18-S, 31-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3660' OL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

Perforated and frap treated

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

3433' TD, 3395' PB.

Perforated 4-1/2" casing with 2, 1/2" JHPF at 3365-70'. Displaced hole with gel water. Spotted 5 barrels of 15% HCl acid across perforations. Pumped 57 barrels of gel water pad and 238 barrels of gel water containing 3% SPG. Flushed with 50 barrels of gel water. Maximum pressure 3700#, average treating pressure 3600#. Formation broke down at 1800#. ISIP 1600#, after 15 minutes 1500#. AIR 26 bpm. Ran 2-3/8" tubing and cleaned out to PB at 3395'. Set tubing at 3380'. Ran rods and pump and placed well on production.

RECEIVED

MAY 7

C. D. BORLAND
ARTESIA, NEW MEXICO

RECEIVED

MAY 12 1970

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED ORIGINAL SIGNED BY
C. D. BORLAND

TITLE Area Production Manager

DATE May 7, 1970

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

ACCEPTED FOR RECORD PURPOSES

MAY 14 1970

Date

ACTING District Engineer

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations; and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian lands should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents, not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; kind or other material placed below, between and above plugs; amount, size, method of packing of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1965 O-685229

SUNDRY NOTICES AND REPORTS ON WELLS

GEOLOGICAL SURVEY

DEPARTMENT OF THE INTERIOR

UNITED STATES

Form 10-65
5-1-65

ORIGINAL SIGNED BY
C. D. BOWLAND

RECEIVED FOR RECORD PURPOSES
MAY 14 1965
U.S. DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT