L™ITED STATES

DEPART. IT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD-Artsia

FORM APPROVED

93

OMB No. 1004-0135

Expires November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

NM-045274 86-941

5. Lease Serial No.

6. Inndian, Allottee or Tribe Name

SUBMIT				If Unit or CA/Agreement, Name and/or No.
	IN TRIPLICATE - O	ther Instructions of	on reverse side	The state of the s
Type of Well	19/20/21/22			
X Oil Well	Gas Well	Other	A P	8. Well Name and No.
2. Name of Operator		— — — — — — — — — — — — — — — — — — —	//5	Hill View AHE Fed Com #3 9. API Well No.
Yates Petroleum Co	orporation /			30-015-20426
3a Address		3b. Phone No. (includ		10. Field and Pool, or Exploratory Area
105 S. 4th Street - A	Artesia, NM 88210	505-748-1471	ARTESIA	\$ <u>/</u>
 Location of Well (Footage, Sec 	c., T.,R., M., or Survey Descrip	otion)		Dagger Draw Upper Penn, S.
660' FSL and 1980' FWL			" " 100 m 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	11. County or Parish, State
Section 23 T20S-R24E			34480	Eddy Co., NM
12. CHECK AI	PPROPRIATE BOX(ES	S) TO INDICATE NAT	URE OF NOTICE, REPORT,	
TYPE OF SUMISSION			TYPE OF ACTION	
Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off
X Subsequent Report	Alter Casing	Fracture Treat	Reclamation	Well Integrity
Final Abandonment Notice	Casing Repair	New Construction	Recomplete	Other
	Change Plans	Plug and Abandon	X Temporarily Abandon	
7	Convert to Injection	Plug Back	Water Disposal	
5/13/02 - Rig up pulling ur 5/14/02 - Set CIBP at 755 Load hole with 2% KCI wa Tested casing to 500 psi 1 Test witnessed by Paul S Well is temporarily abandon	55' capped with 35' cemen ater with 1 gpt corrosion in for 30 minutes and record wartz of BLM.	t. Set CIBP at 6600' cap nhibitor. ed chart. Chart attached	· · · · · · · · · · · · · · · · · · ·	in Period
I hereby certify that the foregoing	is true and correct		Title	