

NO. OF COPIES RECEIVED	4
DISTRIBUTION	
SANTA FE	/
FILE	/ v
U.S.G.S.	
LAND OFFICE	
OPERATOR	9

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

JUL 9 1976

O. C. C.
ARTESIA, OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. OC-605
7. Unit Agreement Name -----
8. Farm or Lease Name Millman Deep Com
9. Well No. 1
10. Field and Pool, or Wildcat Millman Morrow Gas
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Hanagan Petroleum Corporation
3. Address of Operator P. O. Box 1737 Roswell, New Mexico 88201
4. Location of Well UNIT LETTER B 660 FEET FROM THE North LINE AND 1924 FEET FROM THE East LINE, SECTION 4 TOWNSHIP 19S RANGE 28E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3550 KB

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER Pull casing <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plug and abandonment w/tubing in this manner:

6/23/76: P. B. T. D. 10994. Set 4½" bridge plug @ 10500. Circulated hole w/heavy 14 sx class "C" From 10500 to 10365'-Shot 4½" casing off @ 9339'. Plug #2-30 sx-From 9390' to 9290'. 50' in and out of 4½" Stub. Plug #3-35 sx From 7925 to 7825. Plug #4-35 sx from 5850' to 5750'. Plug #5-35 sx from 3600' to 3500'. Plug #6-35 sx From 2825' to 2725', Shot 9 5/8" csg. off at 743', Plug #7, 50 sx From 795' to 695', 50' in and out of 9 5/8" Stub, Plug #8-50 sx From 410' to 310' in and out Surf. csg. & 10 sx plug @ surface with Dry hole Marker at Surface. Heavy Mud between all plugs 6/30/76

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED M. L. Southerland TITLE Agent DATE 7/8/76
APPROVED BY [Signature] TITLE OIL AND GAS INSPECTOR DATE FEB 21 1977
CONDITIONS OF APPROVAL, IF ANY: