

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

**RECEIVED**  
NEW MEXICO OIL CONSERVATION COMMISSION  
**MAR 21 1975**

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

**O. C. C.**  
**ARTESIA, OFFICE**

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>K-3426</b>
7. Unit Agreement Name
8. Farm or Lease Name <b>State "CO" Com</b>
9. Well No. <b>1</b>
10. Field and Pool, or Wildcat Und <b>Dagger Draw Morrow</b>
12. County <b>Eddy</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**  
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☐ OTHER- **DRY**

1. Name of Operator  
**Yates Petroleum Corporation**

2. Address of Operator  
**207 South 4th Street - Artesia, NM 88210**

4. Location of Well  
UNIT LETTER **K** **1980** FEET FROM THE **South** LINE AND **1980** FEET FROM  
THE **West** LINE, SECTION **36** TOWNSHIP **19S** RANGE **24E** NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)  
**3610 GR**

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of completion of any proposed work) SEE RULE 1103.

**TD 9400' - This well was plugged and abandoned as follows:**

9047-9175' - 35 sacks  
8800-8900' - 35 sacks  
7800-7900' - 40 sacks  
6100-6300' - 75 sacks  
3900-4000' - 40 sacks  
2000-2100' - 40 sacks  
950-1050' - 40 sacks  
10 sacks at surface w/dry hole marker.  
Heavy mud between each plug.

The location has been cleaned, pits filled and levelled and is ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Eddie L. Waltrip TITLE Engineer DATE 3-20-75

APPROVED BY John Bergstrom TITLE OIL CONSERVATION INSPECTOR DATE 3-20-75

CONDITIONS OF APPROVAL, IF ANY