State of New Mexico gy, Minerals and Natural Resources Departme.

	Form	C-1	103	
- 1	Revis	ed	1-1	-89

<u>DISTRICT I</u>

OIL CONSERVATION DIVISION

P.O. Box 1980, Hobbs, NM 88240		VITON DIVIC		WELL API NO.		
	2040 Pacheo			30-015-21084		
DISTRICT II	Santa Fe, N	M 87505			 	
P.O. Drawer DD, Artesia, NM 88210				sIndicate Type of Lea	se	
DISTRICT III					STATE	FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410				₅State Oil & Gas Lea	se No.	
SUNDRY N	IOTICES AND REPORTS ON	WELLS				\$ 17 K
(DO NOT USE THIS FORM FOR	PROPOSALS TO DRILL OR TO DE	EPEN OR PLUG BAC	CK TO A	- - - - - - - - - - - - -	Agreement Name	
	ESERVOIR. USE "APPLICATION FO RM C-101) FOR SUCH PROPOSALS				a gradinant name	
Type of Well:	di o-101) I ON GOCIT FROPOSALS	·)		Ivey Com		
OII GAS						
WELL WELL	OTHER	<u></u> .				
2Name of Operator				sWell No.		
Nearburg Producing Company				1		
Address of Operator	Cuito 100 Midland Taura 7070	-		•Pool name or Wildca	at	
4Well Location	2, Suite 120, Midland, Texas 7970	5		Wildcat -Penn		
1	20					
Unit Letter :190	80 Feet From TheNorth	Line and	660	Feet From The	East	Line
	100					
Section 5	- Tourising 120	, tange	26E	NMPM	Eddy	County
	3,368' GR	her DF, RKB, RT, GR, et	C.)			
The same of the man and an address that the same distinct of the same of the s	market to the color of the second of the color of the col				Šalais salaisias salais salais	
11 Checl	k Appropriate Box to Indica	te Nature of No	tice, Rep	ort, or Other D)ata	
	INTENTION TO:	1		SEQUENT RE		
			CODE	DEQUENT INL	FORT OF.	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL W	ORK		ALTERING CAS	ING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE	ORILLING OF	PNS 🗆	PLUG AND ANB	ANDONNENT [
PULL OR ALTER CASING	_ 3 ¬			<u></u>	TEOGRAD AND	ZIADOIAMEIA1
FOLE OR ALTER CASING		CASING TEST	AND CEME	NT JOB		
OTHER:		OTHER:				Г
		-				
12Describe Proposed or Completed Ope work) SEE RULE 1103.	rations (Clearly state all pertinent details, a	and give pertinent dates,	including est	timated date of starting	any proposed	
WORN SEE NOLE 1103.						
Nearburg requests approval	to temporarily abandon the well by	the procedure lister	d below			
ag ,oquotto approva.	to tomporarily abandon the well by	the procedure lister	u Delow.			
 POOH w/production tubin 	ıg.					
2) Set CIBP at 8,809'. New I	ODTO 0 7741					
2) Set CIDF at 0,009. New I	-BID 0,114.				•	
3) RIH w/wireline dump baile	er and dump 35' cement on top of	CIBP.		4	t e	
	•					
 RDMO well service unit. F 	final report. TA'd well.			7		
				Title:	7£	
	- NOO.C.C. m. saf	Hafana I		71 W M	112 SH4	
	- PESSE	lisions time to wi	tness.			
	ラッモア	165%				
I hereby certify that the information abo	ove is true and complete to the best of my l	knowledge and belief.				77
SIGNATURE COO	4 Kimbon C	TITLE Manager	of Drilling	and Production	Z	11/92
OIGIBITURE /	- Land	IIILE IMAIIAYEI	or brilling	and Froduction	DATE	• / / -

SIGNATURE TYPE OR PRINT NAME E. SCO	TITLE Manager of Drilling and Production of Kimbrough	DATE 2/11/98 TELEPHONE NO. (915) 686-8235
(This space for State Use) APPROVED BY	ORIGINAL DE LA CASUM DISTRICT DESCRIPTADE TIME	FEB 3 4 1993
CONDITIONS OF APPROVAL IF A	MV·	