

NEW MEXICO OIL CONSERVATION COMMISSION
DRAWER 10
ARTESIA, NEW MEXICO

FIELD REPORT FOR CEMENTING OF WELLS

Operator <u>Mark Prod Co.</u>		Lease <u>First Natl. Bank</u> <u>Albuquerque</u>		Well # <u>1</u>	
Location of Well	Unit <u>N 50 W</u> <u>180 W</u>	Section <u>8</u>	Township <u>20</u>	Range <u>25</u>	County <u>Eddy</u>
Drilling Contractor	<u>Producers Rly Co.</u>		Type of Equipment <u>Rotary 2. Start approx. 2-10-74</u>		
APPROVED CASING PROGRAM 1-28-74					
Size of Hole	Size of Casing	Weight Per Foot	New or Used	Depth	Sacks Cement
<u>17 1/2"</u>	<u>12 3/4"</u>	<u>32</u>		<u>300</u>	<u>350 cu.</u>
<u>11"</u>	<u>8 5/8"</u>	<u>28</u>		<u>1250</u>	<u>375 cu.</u>
<u>7 1/8"</u>	<u>4 1/2"</u>	<u>10.5+11.6</u>		<u>10000</u>	<u>375</u>
Casing Data:					
Surface <u>39</u> joints of <u>8 5/8</u> inch <u>32</u> # Grade <u>K-55</u> <u>API New</u>					
(Approved) (Rejected)					
Inspected by <u>L. J. Williams</u> date <u>3-6-74</u>					
Cementing Program					
Size of hole <u>11 1/2"</u> Size of Casing <u>8 5/8</u> Sacks cement required <u>550/50</u>					
Type of Shoe used <u>Guide</u> Float collar used <u>Insert Btm 3</u> jts welded <u>2 Threaded</u>					
TD of hole <u>1250 TD</u> Set <u>1241 CL</u> Feet of <u>8 5/8</u> Inch <u>32</u> # Grade <u>K-55</u>					
New-used csg. @ <u>1241 CL</u> with <u>150</u> sacks neat cement around shoe <u>1250 TD</u>					
+ <u>400</u> sax <u>Trinity Lite</u> additives <u>5# Gilsontite</u> <u>4# Floerite</u> <u>2% CC</u> <u>13.0</u>					
Plug down @ <u>6:20</u> (AM) (PM) Date <u>3-6-74</u>					
Cement circulated <u>4/25</u> No. of Sacks <u>25/54</u>					
Cemented by <u>B. J.</u> Witnessed by <u>L. J. Williams</u>					
Temp. Survey ran @ (AM) (PM) Date top cement @					
Casing test @ (AM) (PM) Date					
Method Used Witnessed by					
Checked for shut off @ (AM) (PM) Date					
Method used Witnessed by					
Remarks:					