	· · · · · · · · · · · · · · · · · · ·		· .
D. C. COPIES RECEIVED	R E I	DEN ID	Form C-103 Supersedes Old
TRIBUTION			C-102 and C-103
FE	NEW MEXICO OIL CONSERVATION	GI 1974	Effective 1-1-65
i _E			5a. Indicate Type of Lease
U.S.G.S.	с.	. C. C.	State X Fee
	ARTE	SIA, OFFICE	5. State Oil & Gas Lease No.
OPERATOR		I GFFICE	K-4093
DUNUR (DO NOT USE THIS FORM FOR PROF	Y NOTICES AND REPORTS ON WELLS Sobals to drill or to deepen or plug back to a diffi on for permit -" (form c-101) for such proposals.)	ERENT RESERVOIR.	
1.			7. Unit Agreement Name
OIL GAS WELL	OTHER-		
2. Name of Cperator			8. Farm or Lease Name
Hondo Drilling Com	ipany		Union TX State Com.
3. Address of Operator			9. Well No.
Drawer 2516, Midla	nd. Texas		(Nol
4. Location of Well			10. Field and Pool, or Wildcat
UNIT LETTER N. 6	60 FEET FROM THE South LINE AND	1980 FEET FROM	Wildcat
			THIMMININ (1111)
THE West LINE, SECTIO	N 17 TOWNSHIP 195 RANGE	29E	XIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII
INC. SECTIO			<i>UNNUNUUU</i>
	15. Elevation (Show whether DF, RT, GR,	etc.)	12. County
	3379 RT		Eddy <u>()</u>
16. Check A NOTICE OF IN	Appropriate Box To Indicate Nature of N TENTION TO:		ner Data REPORT OF:
		·	
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL W	0RK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE	DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING		TAND CEMENT JOB	
		Perforated Inter	vals - Test
OTHER		Results	
It Devite Deserved or Completed On	erations (Clearly state all pertinent details, and give	pertinent dates, including	estimated date of starting any proposed
Plan with 4 holes per f 36 Hr Shut In Pressure and Nowsco. Test Result 7/24/74 8:00 A.M. Afte Tubing Conveyed Perfora with 4 holes per ft. at	forated well from 11,362-72 With t. Gas to Surface 55" TSTM. In 2800# - No Water. Well treated s attached. Set Blanking Plug i r killing well, setting Blanking ting Plan was run and the interv 5:30 P.M. on 7/25/74. Results	acreased to 140,0 1 with 1000 Ga. A n Top of Tool @ g plug, Tubing To ral from 11,294 - s of Tests attack	Acid by Western Company 11,343'. ripped, Vann Tool Compan - 11,320' was perforated ned.
failing to kick-off wel circulated with KCL wat	swabbing and testing Perforated l due to an apparent increase in er, The tubing and Tool Assembly	water and less was pulled out	of hole.
Plug and commenced swab interval for the next t vealed less gas and mor		,362 - 11,372'. ing the well to :	flow. Indications re-
11,268-70', Re-ran tubi with 135 Sax of Hallibu and circulated approx:	ng tubing and lower Tool Assembl ng "Stung in" to retainer and so rton recommend cement. Max Pres 15 sacks out of hole with KCL Wa above is true and complete to the best of my knowled stowards in Middle Morrow "B" Zo	queezed entire is ssure 4800# - Pu ater - PBTD 11,20 dge and belief.	lled tubing out of Sting
to periorate selected 1	ntervals in Middle Morrow "B" Zo		BALE 8/12/74
SIGNED	Vice Presio	ient	0/14/14
APPROVED BY W. A. A	USSET TITLE OIL AND GAS I		date <u>AUG 1 2 1974</u>

CONDITIONS OF APPROVAL, IF ANY: