Submit 3 Copies

State of New Mexico Energy, Minerals and Natural Resources Department

-15/
$\sim l l$
\mathbb{N}_{\sim}
Form C 103
Form C (03) Revised 1-1-89

District Office	Chergy, Minicials a	INI I TALLII AI NON	ources Department	•	Keviseu 1-1-95
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSE	RVATION	DIVISION	WELL API NO.	
	j j	P.O. Boy2028	CEINE	30-015-21244	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, N	ew Mexico 8	/304-2086 —	5. Indicate Type of Lease STAT	FEE
DISTRICT III		M	NR 1 0 1997	6. State Oil & Gas Lease No.	FEE
1000 Rio Brazos Rd., Aztec, NM 87410		IVI <i>F</i> -	41/ 10 199/	L-2502	
SUNDRY NOT	ICES AND REPOR	RTS ON MIELE			
(DO NOT USE THIS FORM FOR PR	OPOSALS TO DRILL O	IR TO DEEPEN C	ra peugybacketo	7. Lease Name or Unit Agreen	ent Name
	RVOIR. USE "APPLICA" 0-101) FOR SUCH PRO		Marie Company		
1. Type of Well:				Mesa Com #1	
OIL WELL X	<u>or</u>	HER			
2. Name of Operator				8. Weil No.	
Rhombus Operating Co 3. Address of Operator	., Ltd.			9. Pool name or Wildcat	
200 N. Loraine, Suit	e 1270: Midlan	d. TX 7970	1	Cemetary Morrow	<u> </u>
4. Well Location				000	logt
Unit Letter F: 19	180 Feet From The	North		1980 Feet From The W	lest Line
Section 20	Township 20)S Rans	25 20 E	_{NMPM} Eddy	County
Section 20	10. Elevatio	n (Show whether D	F, RKB, RT, GR, etc.)		
	////// 3507	.1' GR 352	2 RKB		
11. Check	Appropriate Box	to Indicate N	ature of Notice	, Report, or Other Data	
NOTICE OF IN	ITENTION TO:		SI	UBSEQUENT REPORT	*OF:
PERFORM REMEDIAL WORK	PLUG AND ABA	VNDON	REMEDIAL WORK	ALTERING	CASING
					D ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLAN	is 📋	COMMENCE DRILL) ABANDONNILN =
PULL OR ALTER CASING			CASING TEST AND	D CEMENT JOB	_
OTHER:			OTHER:		
12. Describe Proposed or Completed Ope work) SEE RULE 1103.	rations (Clearly state all p	ertinent details, and	l give pertinent dates,	including estimated date of starting an	y proposed
WOTE, SEE ROLL 1103.					
2-18-97 - MIRU. POOH w/ j	oroduction equipment.				
2-18-97 - MIRU. POOH w/ [2-19-97 - Notified Brian w/ C	OCD. Set CIBP @ 840	0'. Circulated h	iole w/ mud & pum	iped 25 sx C cmt 8400-	Post F0-2 3-28-97 P+H
8153'.					3-28-97
2-20-97 - Cut 5-1/2" csg @ 7. 2-21-97 - Worked csg free &	hagan nulling esg.				PLA
a an are 12' to be described as	a DILL w/tha Loade	d hole w/ mud &	& pumped 45 sx C	emt @ 7357'.	1 4 1/
2 24 07 Notified Ligary/OC	D. Togged plug (g) 713	37'. PUCH tO 0	309°, loauea noie v	muu oc pumpeu 15 3x o	
cmt 6569-6393'. Po	OOH to 3300', loaded	hole & pumpea @ 3096'. Circul:	ated hole w/ mud &	& brine, POOH to 1800' &	
2-25-97 - Contacted Brian w	nt 1800-1665'. ND BO	P & wellhead.	RIH w/ tbg to 255'	& pumped 70 sx C cmt	
1C. a. DOOU	e. DD				
3-03-97 - Cut off wellhead as	nd capped well. Instai	led dry noie mai	rker. Leveled cella	n, packaragger rocksom	
	turn and complete to the best :	of my knowledge and	helief.		
I hereby certify that the information above is	2 // ///	or my knowadage and	President	t of the General DATE PAITMEN TELEM	3-5-47
SIGNATURE	n /	clinski		Paither	110 915/0°
TYPE OR PRINT NAME CTC90	y D. Ci	Clins Ki		न्य <u>म्</u>	NUME NO. 113 683
			-		

me Field Rep. 7