

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

MAR 17 1975

O. C. C.

SUNDY NOTICES AND REPORTS ON WELLS, OFFICE

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER- **Dry**

2. Name of Operator  
**Yates Petroleum Corporation**

3. Address of Operator  
**207 South 4th Street-Artesia, NM 88210**

4. Location of Well  
UNIT LETTER **E** **2310** FEET FROM THE **North** LINE AND **860** FEET FROM  
THE **West** LINE, SECTION **9** TOWNSHIP **19S** RANGE **24E** N.M.P.M.

5a. Indicate Type of Lease  
State ☒ Fee ☐

5. State Oil & Gas Lease No.  
**K-4326**

7. Unit Agreement Name

8. Farm or Lease Name  
**State "DQ" Com**

9. Well No.  
**1**

10. Field and Pool, or Wildcat  
**Wildcat**

12. County  
**Eddy**

15. Elevation (Show whether DF, RT, GR, etc.)  
**3721' GR**

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged and Abandoned Well As Follows:

Set bottom plug w/25 sacks of cement over perforations 6406½-22½ and cut off 4½" casing at 5686' and pulled same, set the following plugs:

5686-5586'	35 sacks
3400-3500	35 sacks
1650-1750	35 sacks
800-900	35 sacks
15 sacks at surface with dry hole marker.	

Heavy mud between plugs.

The location will be clean and leveled, pits filled and will we will notify your office when ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED C. J. Loyd TITLE Supt. Prod. DATE 3-14-75

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: