

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

RECEIVED

APR 3 1975

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> P&A		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator Harvey E. Yates Company, Inc.		5. State Oil & Gas Lease No.
3. Address of Operator Suite 1000 Security Nat'l Bank Bldg., Roswell, New Mexico 88201		7. Unit Agreement Name
4. Location of Well UNIT LETTER <u>F</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>2</u> TOWNSHIP <u>19S</u> RANGE <u>30E</u> NMPM.		8. Farm or Lease Name Aztec State
15. Elevation (Show whether DF, RT, GR, etc.) 3550 GR		9. Well No. #1
		10. Field and Pool, or Wildcat Shugart
		12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103 ID 3060

Ran tubing to 2760' and circulated gel, spotted 35 sx plug from 2760' to 2660'
spotted plug with 35 sx from 2300' - 2400'. spotted plug from 1950' - 1850'
spotted 35sx plug from 720' to 820'
15' plug at surface. P+A 3-23-75

Csg. left in hole - 8 7/8" - 871
7" from 2460 to 3060

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED James D. Monroe TITLE _____ DATE 2 April 75

APPROVED BY Debra Monroe TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: