Form 3160-5 (November 1983) (Formerly 9-331)

UN'TED STATES OF THE INTERIOR verse side)

SUBMIT IN TRIP ATE (Other instruction

orm approved. Budget Bureau No. 1004-0135 Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO.

BUREAU OF LAND MANAGEMENT

SUNDRY	NOTICES	AND	REPORTS	ON	WELLS

NM-19418

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

(Do not use this fo	orm for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	
OIL C GAS C	1	7. UNIT AGREEMENT NAME
WELL GAS WELL	OTHER	
2. NAME OF OPERATOR		8. FARM OR LEASE NAME
Barbara Fasker	1	Feil Federal
3. ADDRESS OF OPERATOR		9. WELL NO.
303 W. Wall, S	Suite 1900, Midland, Texas 797@ECEIVED	1
1. LOCATION OF WELL (Re	port location clearly and in accordance with any State requirements.*	10. FIELD AND POOL, OR WILDCAT
See also space 17 below At surface	OCT 2 5 1991	Cemetery (Morrow)
	O. C. D.	11. SEC., T., R., M., OR BLK. AND SURVEY OR ARMA
Unit D, 660' i	NL & 660' FWL, Sec. 28, T-20-9, TESL 250 EFIC:	Sec. 28, T-20-S, R-25-E
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
	35261 GI	Fddv New Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF:				
	r		(1	
EST WATER SHUT-OFF		PULL OR ALTER CASING		WATER SHUT-OFF		REFAIRING WELL	
RACTURE TREAT		MULTIPLE COMPLETE		FRACTURE TREATMENT		ALTERING CASING	
SHOOT OR ACIDIZE		ABANDON*		SHOOTING OR ACIDIZING	X	ABANDON MENT*	<u> </u>
EPAIR WELL		CHANGE PLANS		(Other)			L
Other)						of multiple completion on Well	i

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

12-20-90 thru 1-02-91

16.

- Perforated additional Morrow pay with 2 JSPF as follows: 9527-32', 9514-24', 9494-9504', 9470-74', 9458-61', 9436-38', 9431-33'.
- Perforated Atoka pay with 2 JSPF as follows: 9341-45', 9329-32', 9311-15', 9292-94', 9270-75', 9263-66', 9155-61', 9133-43'.
- Swabbed well and established flow. 3.
- Put Morrow zone on line to NGPL.

This report replaces report filed 1-21-91 and corrects zones perforated.

