New Mexico

ENERGY, MINERALS AND NATURAL RESOUR . ES DEPARTMENT

OIL CONSERVATION DIVISION ARTESIA DISTRICT OFFICE

GARY E. JOHNSON Governor JENNIFER SALISBURY Cabinet Secretary

DECEMBER 4, 1998

K.W. CHEW
I.T. PROPERTIES
3502 YACHTCLUB CT.
ARLINGTON, TEXAS 76106

PACKER LEAKAGE TEST: F-23-19-28 DHY STATE #1

DEAR MR. K.W. CHEW

I HAVE NOT RECIEVED ANY C-103'S SHOWING THE DHY STATE #1 HAS BEEN REPAIRED AS WAS YOUR INTENTION TO PER OUR PHONE CONVERSATION JULY 9, 1998.

PACKER LEAKAGE TEST WERE DUE BY OCTOBER 15, 1998 ON ALL DUAL GAS WELLS.

PLEASE REACH ME BY PHONE OR LETTER BY JANUARY 4, 1998. I NEED TO KNOW THE STATUS OF WELL REPAIR AS REQUESTED PREVIOUSLY.

ALSO A PACKER LEAKAGE TEST MUST BE RAN ON THE DHY STATE #1.

IF YOU HAVE NO FUTHER INTENTIONS OF PRODUCING THE DHY STATE #1. IT NEEDS TO BE BROUGHT IN TO COMPLIANCE WITH RULE 201 B. A WELL SHALL BE EITHER PROPERLY PLUGGED AND ABANDONED OR TEMPORARILY ABANDONED IN ACCORDANCE WITH THESE RULES WITHIN 90 DAYS AFTER.

- (1) A 60 DAY PERIOD FOLLOWING SUSPENION OF DRILLING.
- (2) A DETERMINATION THAT THE WELL IS NO LONGER USABLE FOR BENEFICIAL PURPOSES.
- (A) A PERIOD OF 1 YEAR IN WHICH A WELL HAS BEEN CONTINIOUSLY INACTIVE.

SINCERELY,

Michael C. Smithefield

MICHAEL C. STUBBLEFIELD FIELD REP. 2

Z 212 312 949



Receipt for
Certified Mail
No Insurance Coverage Provided
Do not use for International Mail
(See Reverse)

Section to K.W. Chew, I.T. 3502 Yachtel. Arlington Tx 1 stage 1 and a managery of	26106
a Citing and	\$.32
100 0 making in	2.45
restricted to the second	
Complete Sound And South Jewener	
Reduce Pacerot Schwing to Whole later and Adurk sieels Address	
1. TAL 1 stage 5. oraș	\$2.77
fullmark or Dan 12-7-98	/