

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☐ other ☐ Depleted Gas Well

2. NAME OF OPERATOR

Penroc Oil Corporation /

3. ADDRESS OF OPERATOR

P. O. Drawer 831, Midland, Texas 79702

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1980' fSL, 1980' fEL

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

☐
☐
☐
☐
☒
☐
☐
☒

5. LEASE

NM-0428657

6. IF INDIAN, ALLOTTEE OR TRIBE NAME **RECEIVED**

7. UNIT AGREEMENT NAME

JUN 8 1981

8. FARM OR LEASE NAME

Arco-Federal

9. WELL NO.

1

10. FIELD OR WILDCAT NAME

Winchester Atoka (Gas)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

33-19S-28E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

14. API NO.

30-015-21731

15. ELEVATIONS (SHOW DF, KDB, AND WD)

3335 DF, 3336.3 KB

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 12-28-80 Go in hole w/4 1/2" CIBP, set @ 9500'. Bailer dump 35' cement plug on top CIBP.
- 12-29-80 Shoot off 4 1/2", 11.60#, N80 casing @ 8997'. Recover 284 jts being 8997'.
- 1-2-81 Set 150' cement plug 8925'-9075' (75' in and out of 4 1/2" csg. stub.) WOC 4 hrs. Tag top of plug @ 8905'.
- 1-4-81 Set 150' cement plug 6400'-6550'
Set 100' cement plug 4065'-4165'
Set 100' cement plug 2550'-2650' (50' in & out of 8 5/8" csg. bottomed @ 2600').
- 1-5-81 Set 15 sack cement plug in surface casing. Installed dry hole maker. When all surface equipment is removed and location has been leveled, ripped, cleaned etc. according to BLM Stipulations, your office will be notified that location is ready for inspection for Final Abandonment approval.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

P. J. Dally

TITLE

President

DATE

1-25-81

APPROVED

(This space for Federal or State office use)

APPROVED BY

(Orig. Sgd.) PETER W. CHESTER

DATE

CONDITIONS OF APPROVAL, IF ANY

JUN 26 1981

FOR

JAMES A. GILLHAM
DISTRICT SUPERVISOR

See Instructions on Reverse Side