	OF NEW MEXICO ID MINERALS DEPARTMENT <u>APPLICATIO</u>	O., CONSERVATION D P. O. Box 200 Santa Fe, New Mer N FOR CLASSIFICATION	88 100 87501	APR 303 O. C. D WELL ARTESIA, OI	).
erator	PENROC OIL CORF		tact Party _ <b>ST</b>		
idress 🖌	0 DRAWER 831, MIL	DLAND, TEXAS 797	92 Phone	No. 915-683-	1861
ase A	VGELL RANCH Well	No. / UT 8	Sec. 33 TWP	<b>195</b> RGE	28E
oj Hame	WINCHESTER- MOI	ROW GAS Mini	mum Rate Reques	ted 350 MC	FGPD
unsport	er Name <u>EL PASO NA</u>	TURAL GAS CO. Put	chaser (if diff	erent)	
e you s	seeking emergency_"hard	ship" classification	for this well?	X yes	no
	must provide the foll tries as a hardship ga		support his co	ntention that (	the subject
waste	de a statement of the " will occur if the su ice. (The definition o	bject well is shut-ir	or is curtaile	d below its ab:	ility to
Docum elimi	nent that you as applic .nate or prevent the pr	ant have done all you oblem(s) leading to t	reasonably and his application	economically o	can do to
ā)	Well history. Explain attempts have been mad	fully all attempts m e, explain reasons fo	ade to rectify or failure to do	the problem. I	lf no
b)	Mechanical condition o mechanical attempts to	f the well(provide we rectify the problem,	including but	Explain fully not limited to:	/ :
	<li>i) the use of "smallb lift, rod pumping</li>	ore" tubing; ii) othe units, etc.	er de-watering d	evices, such as	s plunger

į

;

Present historical data which demonstrates conditions that can lead to waste. Such data should include:

- a) Permanent loss of productivity after shut-in periods (i.e., formation damage).
- b) Frequency of swabbing required after the well is shut-in or curtailed.
- c) Length of time swabbing is required to return well to production after being shut-in.
- d) Actual cost figures showing inability to continue operations without special relief

If failure to obtain a hardship gas well classification would result in premature abardonment, calculate the quantity of gas reserves which would be lost

Show the minimum sustainable producing rate of the subject well. This rate can be determined by:

- a) Minimum flow or "log off" test; and/or
- b) Documentation of well production history (producing rates and pressures, as well as gas/water ratio, both before and after shut-in periods due to the well dying, and other appropriate production data).

Attach a plat and/or map showing the proration unit dedicated to the well and the ownership of all offsetting acreage.

- E Submit any other appropriate data which will support the need for a hardship classification.
- ) If the well is in a prorated pool, please show its current under- or over-produced status.
- ) Attach a signed statement certifying that all information submitted with this application is true and correct to the best of your knowledge; that one copy of the application has been submitted to the appropriate Division district office (give the name) and that notice of the application has been given to the transporter/purchaser and all officet operators.