NO. OF COPIES RECEIVED	13			Form C-103
DISTRIBUTION			RECEIVED	Supersedes Old C–102 and C–103
INTA FE	1		NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE	1	V		
U.S.G.S.		_	JUN 8 1977	5a. Indicate Type of Lease
LAND OFFICE				State X Fee
OPERATOR	1		0.c . c	5. State Oil & Gas Lease No.
			D. C. C.	K-6774
(DO NOT USE THIS FO USE	SUI		RY NOTICES AND REPORTS ON WELLS prosals to drill or to deepen or plug back to a different reservoir. Ton for permit -" (form C-101) for such proposals.)	
	Ω.			7. Unit Agreement Name
	X		0THER-	
Name of Operator				8. Farm or Lease Name
Coquina Oil Corporation 🗸				Bass State
· Address of Operator				9. Well No.
P. O. Drawer 2960, Midland, Texas 79702				ן 'ז
Location of Well				10. Field and Pool, or Wildcat
UNIT LETTERE	Undesignated			
				$\boldsymbol{\forall} \boldsymbol{)} \boldsymbol{(} \boldsymbol{)} \boldsymbol{(}$
THE West	INE, S	ECTI	ON 32 TOWNSHIP 19-S RANGE 29-E NMPM.	
MANANAN MARKANAN MAR	$\overline{(U)}$	Π	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	III	$\prime\prime\prime$	3280 GR	Eddy
16.	Che	ck	Appropriate Box To Indicate Nature of Notice, Report or Oth	ner Data
				REPORT OF:
PERFORM REMEDIAL WORK			PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON]		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING			CHANGE PLANS CASING TEST AND CEMENT JOB	
			OTHER <u>Explanation</u>	<u>of Tubing X</u>
OTHER				
			parations (Clearly state all pertinent details, and give pertinent dates, including	entireted data of starting and proposed

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Ran 4 1/2" csg to 11,500'. Cemented with 300 sxs Class H cement. Top of cement 8620'. Perforated Morrow zone 11,282-88', 11,294-305', 11,312-18'. Tested Morrow . Recovering gas & water. Found Morrow to be non-commercial. Set CIBP @ 10,560'. Dumped 20' cement on top of BP. Perforated Strawn from 10,470-80' & 10,455-58' w/2 JSPF. Acidized with 1000 gals 15% NEA. Set RBP @ 10,430' & perforated Strawn 10,370-94' w/2 JSPF. Acidized w/1000 gals 15% NEA. Moved RBP to 10,350'. Perforated Strawn 10,327-34', 10,298-310', 10,258-270' w/2 JSPF. Acidized w/2000 gals 15% NEA. POOH w/RBP. Went in hole with production packer & sliding sleeve. Set packer at 10,356.48'. It was our intention to re-stimulate the lower two sets of Strawn perforations, open the sleeve & put all of the Strawn together. After swabbing in the lower two sets of Strawn, the well was good enough that additional treatment was not necessary. The sleeve was opened & all of the Strawn was put together.

fs 10455-80 atoka

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Engineering Assistant DATE June 3, 1977 TITLE JUN 1 0 1977 SUPERVISOR. DISTRICT H

CONDITIONS OF APPROVAL, IF ANY: