Ferm 3160-5 (August 1999)	U	ED STATES				Cl	
		T OF THE INTERIO		ons.	OMB No. 1004-0135 Expires November 30, 2000		
			N.M. DI	V-Dister	ial No.		
	Do not use this form for	AND REPORTS ON proposals to drill or to	re-enter an ISUI VV. GI	rand Avenu	i ç		
а	bandoned well. Use For	m 3160-3 (APD) for suc	h proposals. Artesia, N	VM 88210	llottee or Tribe Name		
				N/A	N/A 7. If Unit or CA/Agreement, Name and/or No.		
		Athan Instructions on the	warea side	N/A	JAVAgreement, Name and	OF NO.	
Type of Well	SUBMIT IN TRIPLICATE - Other Instructions on reverse side				8. Well Name and No.		
Oil Well Gas Well Other Injection 2. Name of Operator Yates Petroleum Corporation /				ALLISO	N CQ FEDERAL #	3	
				9. API Well 30-015-2			
Yates Petroleum Co	prporation /	3b. Phone No. (inclu	de area code)		Pool, or Exploratory Area		
105 S. 4th Street - Artesia, NM 88210 505-748-1471							
4. Location of Well (Footage, Se		iption)	and the second second		IK WOLFCAMP		
660' FSL & 2310' FWL	Section 15-T	19S-R24E UNIT	N				
			1. 1. 1. 1. 202 - 201 U		OUNTY, NM		
12. CHECK APPF	ROPRIATE BOX(ES) TO I	NDICATE NATURE OF	NOTICE, REPORT, OR OTHER TYPE OF ACTION				
X Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-	Dff		
		Fracture Treat		Well Integrity	,		
Subsequent Report	Alter Casing			• ·			
Final Abandonment Notice	Casing Repair	New Construction	Recomplete	Other		<u> </u>	
	Change Plans	X Plug and Abandon	Temporarily Abandon				
	Convert to Injection	Plug Back	Water Disposal				
NOTIFY NMOCD 24 HOU 1. MIRU WSU; RU safety tubing from YPC yard. TIH 2. RU wireline to se CIBP across Cisco perfs. Pull tu 3. Spot 15 sk plug from 37 4. Spot 75 sk plug from 19 6. Spot 15 sk plug from 19 6. Spot 15 sk plug from 16 7. Spot 15 sk plug from 16 7. Spot 15 sk Class C cerr 8. Remove all surface equit	JRS BEFORE STARTING equipment. No casing reco t to retrieve RBP @ 6620' @ 8762' & cap w/ 35' cem bing up hole & circ clean. 1 '60' - 3860' across Abo top 219-2911' across Yeso per 340'-2040' across intermed 50'-260' across surface cas hent plug @ surface. ipment & wel dry hole mark	PLUGGING OPERATIC overy will be attempted. To - POH. TIH to retrieve pa ent. Spot 30 sk plug from WOC 4 hrs & tag plug @ @ 3810'. Circ tubing clean, fs. Circ tubing clean, WO iate casing shoe @ 1990' sing shoe @ 210'. Circ tub	OH w/ 2-3/8" tubing. Inspect tub icker @ 8825' - POH. 8444' - 8713' across Atoka perf	bing & if necessary p is & a 20 sk plug froi et if necessary. essary. s - tag plug - rese t i	rocure needed m 6454-6585'		
Name (Printed/Typed) Operations Technici Donna Clack Operations Technici				ian			
Signature	10.	· · ·	Date		<u> </u>		
Alann	a cla	Ck 👫	4-26-02				
	······································	THIS SPACE FOR FED	ERAL OR STATE OFFICE USE				
Approved by		£	Title		Date		
Conditions of approval, if any, are the applicant holds legal or equita applicant to conduct operations th		does not warrant or certify that ect lease which would entitle the	e Office				
Title 18 U S C Section 1001 and	Title 43 U S C. Section 1212, ma		wingly and willfully to make to any depart	ment or agency of the Un	ited States any false, fictitious		
	sentations as to any matter within						

F