

Summary of Control

1st Control: 1250 to 30/30 Pozmin - Class C w/100 Gals
Followed by 100 in Class C heat.

2nd Control: 1500 to 30/30 Pozmin Class C w/100 Gals
Followed by 200 in Class C heat.

3rd Control: 1750 to 30/30 Pozmin Class C w/100 Gals
Followed by 200 in Class C heat.

4th Control: 2000 to 30/30 Pozmin Class C w/100 Gals
Followed by 200 in Class C heat.

5th Control: 2250 to 30/30 Pozmin Class C.

Area program:

0' to 700': Fw speed mud

700' to 8500': 9.25 - 10.00 gpm

8500' to 9500': 9.25 - 9.50 gpm

9500' to 12150': Call out & stop pac for
Wt loss mud in
Wt. Disposal

12150' to 13000': 8.4 - 9.2 w/100 Gals
for Wt loss mud 10%