Submit 3 Copies to Appropriate District Office

State of New Mexico Energ 1 Inerals and Natural Resources Department

Form C-	103
Revised	1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION

	Weather 1.1.03	L
L API NO.		

P.O. Box 1980, Hobbs, NM 88240	P.O. Box 2088		30-015-22435	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico		5. Indicate Type of Lease STATE FEE X	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.	
(DO NOT USE THIS FORM FOR PROF DIFFERENT RESERV (FORM C-1	ES AND REPORTS ON WEL COSALS TO DRILL OR TO DEEPEN FOR. USE "APPLICATION FOR PER 11) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name	
1. Type of Well: OIL GAS WELL X WELL	OTHER	- o = nn	Ross IZ Com	
2. Name of Operator	3	ECEIVE	Meli No.	
YATES PETROLEUM CORPORA	TION U U		9. Pool name or Wildcat	
3. Address of Operator 105 South 4th St., Arte	sia, NM 88210	FEB 2 4 1995	Undesignated Canyon	
4 Well I cention	Feet From TheNorth	LCON. DI	Feet From The West Line	
Section 28		inge D185E, 2	NMPM Eddy County	
	350	02 KB	<u> </u>	
II. Check A	appropriate Box to Indicate I	Nature of Notice, R SUB	eport, or Other Data SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT		
PULL OR ALTER CASING		CASING TEST AND CE	—	
OTHER:		OTHER: Perfora	te & acidize Canyon X	
work) SEE RULE 1103. 2-22-95 - Rigged up wi holes (2 SPF) as follo 02, 42, 46, 49, 52, 54 TIH with RBP, packer a packer at 7766'. Spot set packer at 7735'. and ball sealers. Uns up and reset RBP at 73 perforations 7640-7702 packer at 7579'. Drop	reline. TIH with 4" ows: 7640, 42, 44, 60 or, 56, 58 & 7760'. TO end tubing to 7797'. oted 1 barrel 20% acid of Acidized perforations set packer at 7735'. oted 12000 gallons opped down and unset RI otes packer at 7579'.	casing guns and 0, 62, 64, 68, 700H with casing Set RBP at 7797 dacross perfora 5 7742-7760' with Dropped down ar 00 psi. Set page gelled 20% NEFF BP at 7735'. Dropped installed Unset RBP at	I perforated 7640-7760' w/48 .52" 70, 72, 84, 86, 94, 96, 98, 7700, guns and rigged down wireline. 7'. Tested to 1000 psi. Set ations 7742-7760'. Moved up and the 2000 gallons 20% NEFE acid and unset RBP at 7797'. Moved eker at 7579'. Acidized E acid and ball sealers. Unset ropped down to 7797' and set d flange. Swabbing. 7797'. TOOH with tubing, packer	
I hereby certify that the information above is that	and complete to the best of my knowledge an	d belief.	0.02.05	
SIGNATURE Lustry	Clin I	me Production	Clerk 2-23-95 TELEPHONE NO. 505/748-147	
TYPEOR PRINT NAME Rusty Klein			TELEPHONE NO. 303/140 141	
(This space for State Use)	FARE BY IIM YE ROM TO SEE BOOK		MAR 9 1995	

APPROVED BY ---