JUL 3 0 1993

QI.D.

FILE: GREENA BRIEF A VM/XA SP 2.1 CMS 5.6

GREENWOOD PRE-GRAYBURG UNIT FEDERAL "A" COM NO. 1 PLUG AND ABANDON SHUGART MORROW FIELD EDDY COUNTY, NEW MEXICO

- 1. RUSU X POH W/ PROD EQUIP.
- 2. SET CIBP AT 11,450' X CAP W/ 35' CMT.
- 3. LOAD HOLE W/ MUD.
- 4. SET CIBP AT 11,000' X CAP W/ 35' CMT.
- 5. LOAD HOLE W/ MUD.
- 6. SPOT 100' CMT PLUG FROM 4650' TO 4550'.
- 7. LOAD HOLE W/ MUD.
- 8. SPOT 100' CMT PLUG FROM 815' TO 715'.
- 9. LOAD HOLE W/ MUD.
- 10.CAP W/ 15 SX CMT PLUG AT SURFACE.

IF YOU HAVE ANY QUESTIONS, PLEASE CONTACT:

 WORK
 USERID
 HOME

 BRIAN TAYLOR
 8-321-7301
 ZBWT03
 713-578-7501

 TERRY CALDWELL
 8-321-7286
 ZTAC17
 713-975-9863