# 7. UNDESTRABLE EVENTS:

A. Immediate notice is required of all blowouts, fires, spills, and accidents involving life-threatening injuries or loss of life. (See NTL-3)

#### 8. CASING:

- A. Notify the District Office in sufficient time for a representative to inspect any used casing planned for use in a casing string.
- B. Prior to drilling the plug after cementing, all casing strings shall be pressure tested. Test pressure shall not be less than 600 psi for surface casing, and a minimum of 1,500 psi or 0.2 psi/ft., whichever is greater, for other casing strings. If the pressure declines more than 10 percent in 30 minutes, or if there is other indication of a leak, the casing shall be recemented, repaired, or an additional casing string run, and the casing shall be tested again in the same manner.

## 9. WAITING ON CEMENT TIME:

A. After cementing but before commencing any test, the casing string shall stand cemented under pressure until the cement has reached a compressive strength of at least 500 psi at the shoe, except that in no case shall tests be initiated until cement has been in place at least 8 hours. WOC time will be recorded in the driller's log.

# 10. DRILLSTEM TESTS:

A. Estimated amounts of oil and gas recovered and/or produced during drillstem tests are to be shown in the driller's log and reported in accordance with NTL-4.

### 11. FLARING GAS:

- A. Approval is granted to flaregas while drilling and testing.
- B. Failure to request permission to vent any gas after well is completed may result in compensation due the United States being the full value (100% royalty) of the gas so wasted. (See NTL-4)

# 12. SAFETY:

- A. All rig heating stoves are to be of the explosion-proof type.
- B. Drilling rig engines should have water cooled exhausts.
- C. Rig safety lines are to be installed.
- D. Hard hats must be utilized.