				RECEIVED		
		BYRON JACKS	ON INC.	DEC 1 1 1978		
	· · · · · · · · · · · · · · · · · · ·	CEMENTING A	FFIDAVIT	RTESIA, OFFICE		
he facts here on <u>12-</u> operation here Well No	in below set , 19_ ein described / on	out do state 28, BYRON JI for <u>SoJTh/</u> the <u>ST</u>	e: I am employ ACKSON INC. pe AND Roy 14	lease		
located in	ddy	County,	State of <u>Ve</u>	<u>w mexico</u> . 14-19-29		
250 <u>5x</u> 250 <u>5x</u>	<u>5 uRe F-111</u> "C"	<u> </u>	2 <u>70 CA/CI</u>	im Chloride		
An estimated_	sa	cks of exces	s cement was c	circulated out of the w	ell	
hole size was this job the	s following ma	inches, and terials were	used to place	Company states that thas <u>feet</u> . For set, for the state of the state o		
Plug from	ft. to	ft	. with	sacks of		
است						

.