

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

# NEW MEXICO OIL CONSERVATION COMMISSION

OCT 11 1979

O.C.C.

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. 648

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- 2. Name of Operator Southland Royalty Company ✓ 3. Address of Operator 1100 Wall Towers West, Midland, Texas 79701 4. Location of Well UNIT LETTER B, 660 FEET FROM THE north LINE AND 1980 FEET FROM THE east LINE, SECTION 32 TOWNSHIP 19-S RANGE 28-E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 3366.9' GR	7. Unit Agreement Name 8. Farm or Lease Name State "32" Com. 9. Well No. 1 10. Field and Pool, or Wildcat Winchester Undesignated (Morrow) 12. County Eddy
--	--

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

#### NOTICE OF INTENTION TO:

#### SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spud well by Hondo Drilling Company Rig #3 @ 6:00 P.M. 10-2-79.  
Drill 15" hole to 360'. Ran 11 3/4" 42# H-40 ST&C csg set @ 360'.  
Cement with 375 ox Class C 2% gel cement. Plug down @ 8:50 A.M. 10-3-79.  
Circulate 60 ox cement to surface. WOC 18 hrs.  
Install 10" double Ser 900 BOP. Test BOP and csg to 1000 psi for 30 min. Hold OK  
Drill ahead 11" hole.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>C. Harney Carr</u>	TITLE <u>District Engineer</u>	DATE <u>10-4-79</u>
APPROVED BY <u>W. A. Gressett</u>	TITLE <u>SUPERVISOR, DISTRICT 1</u>	DATE <u>OCT 12 1979</u>
CONDITIONS OF APPROVAL, IF ANY:		