## HINTES STATES STEMIT IN TRIFF. Form approved.

(May 1960)	DEPARTMEN C. THE IN  GEOLOGICAL SURV	Budget Bureau No. 42-R1424.  5. LEASE DESIGNATION AND BERIAL NO. NM. 9805-A			
SUNE	6. IF INDIAN, ALLOTTE	E OR TEIBE NAME			
OIL CAS WELL T	OTHER	DEC 1 2 1979	7. UNIT AGREEMENT NAME		
2. NAME OF OPERATOR	Max Wilson, Inc.	C. C. C.	8. FARM OR LEASE NAME  Kevin Wildernhel		
P.O. Drawer 1978 - Roswell, NM			9. WELL NO. =	-	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*  See also space 17 below.)  At surface			10. FIELD AND POOL, OE WILDCAT Wildcat		
1,980' FWL & 506' FNL - Sec. 6 T.20S, R.23E			11. SEC., T., E., M., OR BLE. AND SURVEY OR AREA  6 - 20S - 23E		
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, AT, GR, etc.)  4,222 GR			13. STATE NM	
16.	Check Appropriate Box To India	cate Nature of Notice, Report, or C	Other Data		
NOTICE OF INTENTION TO: SUBSEQ			GENT REPORT OF:		
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS	(Other)	REPAIRING WELL  ALTERING CASING  ABANDONMENT*  of multiple completion on Well		
(Other)  17. DESCRIBE PROPOSED OR proposed work. If nent to this work.) *	COMPLETED OPERATIONS (Clearly state all p well is directionally drilled, give subsurfa	Completion or Recomplertinent details, and give pertinent dates, ce locations and measured and true vertical	etion Report and Log for including estimated dat il depths for all markers	e of startium any	

Per verbal instructions of George Stewart 11-29-79:

Set 100' plug from 1,970' to 2,070' Set 100' plug from 2,200' to 2,300' 20 sx at top with regulation marker Pull  $4\frac{1}{2}$ " casing above 2,400'

DEC 1 0 1979

U.S. GEOLUGICAL SURVEY ARTESIA, NEW MEXICO

is. I hereby capity that the foregoing of true and correct				
SIGNED MAY TOPPON TIT	E Operator	_ DATE _	12-6-79	
(This space for Federal or State office use)  (Crig. Sgd.) GEORGE H. STEWAR THE CONDITIONS OF APPROVAL, IF ANY:	JB	_ PATE _	14. 0 1979	