

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

# OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

FEB 17 1994

WELL API NO. 30-015-22953
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. L-5033
7. Lease Name or Unit Agreement Name Amoco State HE
8. Well No. 1
9. Pool name or Wildcat Artesia Queen Grayburg San Andres

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> P & A Well	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3482' GR
2. Name of Operator YATES PETROLEUM CORPORATION	
3. Address of Operator 105 South Fourth Street - Artesia, NM 88210	
4. Well Location Unit Letter <u>K</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>11</u> Township <u>19S</u> Range <u>27E</u> NMPM <u>Eddy</u> County	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-14-94 - Moved in and rigged up plugging equipment. POOH w/rods and tubing. RIH with tubing. Loaded hole with mud. Pulled and laid down tubing to 1702'. Spotted a 40 sack cement plug from 1702-1552'. Pulled up and shut down for weekend.

2-15-94 - WIH and tagged top of cement at 1496'. Pulled and laid down tubing to 554'. Spot a 25 sack cement plug from 554-414'. Pulled and laid down tubing to 150'. Spot a 25 sack cement plug from 150' to surface. Dug out cellar and cut off wellhead. Installed regulation abandonment marker. PLUGGED AND ABANDONED - FINAL REPORT.

Post ID-2  
2-25-94  
P4A

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE Feb. 16, 1994

TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505-748-1471

(This space for State Use)

APPROVED BY Rusty Klein TITLE OIL AND GAS INSPECTOR DATE JUL 12 1994

CONDITIONS OF APPROVAL, IF ANY: