

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION
RECEIVED

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

DEC 27 1979

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Parino Com.
9. Well No. 1
10. Field and Pool, or Wildcat Wildcat Morrow
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK ANY PERMANENT RESERVOIR. USE APPLICATION FOR PERMIT - "A" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/>	GAS WELL <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>
Name of Operator Amoco Production Company		
Address of Operator P. O. Box 68, Hobbs, NM 88240		
Location of Well UNIT LETTER <u>I</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>23</u> TOWNSHIP <u>19-S</u> RANGE <u>25-E</u> NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.) 3417.2 GR		

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged and abandoned well by the following procedure:

Spotted a 100 sx Class H cement plug from 9500'-9660'.
Spotted a 100 sx Class H cement plug from 9180'-9380'.
Spotted a 100 sx Class H cement plug from 8800'-9000'.
Spotted a 100 sx Class H cement plug from 8140'-8340'.
Spotted a 100 sx Class H cement plug from 7618'-7818'.
Spotted a 75 sx Class H cement plug from 6535'-6685'.
Spotted a 75 sx Class H cement plug from 3775'-3925'.
Set a cast iron bridge plug at 2490' and capped with 35' cement.
Spotted a 50 sx Class H cement plug from 367'-467'.
Spotted a 20 sx Class H cement surface plug.

Erected permanent P x A marker. Clean and level location. Will advise when location is ready for final inspection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Bob Davis TITLE Assist. Admin. Analyst DATE 12-26-79

APPROVED BY [Signature] TITLE OIL AND GAS INSPECTOR DATE AUG 4 1980

CONDITIONS OF APPROVAL, IF ANY:
0+4 NMOC-A, 1-Hou, 1-Susp, 1-BD