

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

MAY 18 1981

O.C.D.
ARTESIA OFFICE

3a. Indicate Type of Lease
State ☒ For ☐
5. State Oil & Gas Lease No.
LG-5096

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐	GAS WELL ☒	OTHER ☐
Name of Operator		
Gulf Oil Corporation		
Address of Operator		
P. O. Box 670, Hobbs, NM 88240		
Location of Well		
UNIT LEFT	E	1980 FEET FROM THE North LINE AND 660 FEET FROM
THE West	LINE, SECTION 30	TOWNSHIP 19S RANGE 29E NMPM.

7. Unit Agreement Name
8. Form or Lease Name
Eddy "IL" State Com
9. Well No.
1
10. Field and Pool, or Wildcat
Atoka
12. County
Eddy

15. Elevation (Show whether DF, RT, GR, etc.)

3323' GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
FULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	
OTHER ☐		OTHER P&A Morrow, perf, acidize	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POH with production equipment. Set CIBP at 11,010', dump 35' cement on plug; test casing 500#. Perf 10,414'-10,436' with (1) 1/2" burrless JHPF (22 holes). Acidize 10,414'-10,436' with 6000 gals 10 1/2% slick Morrow acid and (12) 7/8" RCNB's. ISIP 4300#, 5 min 3600#, 15 min 1500#. Now doing study for compressor.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED RDP Riche TITLE Area Engineer DATE 5-15-81

SUPERVISOR, DISTRICT II

MAY 20 1981