

30-05-23081

3-12-80

Samma-Ray Hunt

1400-3846

3-14-80

Comp. Pensilva  
Hunt

Comp  
660-5008

146-2422



76 P. H 2554 2600  
load w/mud 2554 1700  
tag down plug 2554 350  
surface plug w/marker.

either by 5 1/2" @ 350 -  
Pump down hole side or 1"  
+ get plug @ top of salt.  
5 1/2" 3850 - 675 to c 750

---

