

April 1, 1980 Tres Amigos No. 1

8:00 AM Rigged up Clarke Unit.

9:00 AM TP 30# FL 400' from surface. Ran swab to 1600'. Rec. drilling mud.

10:00 AM TP 0# FL 800' from surface. Ran swab to 2200'. Rec. drilling mud.

11:00 AM TP 0# FL 900' from surface. Ran swab to 3500'. Rec. gas, drilling mud & oil.
Getting quite a bit of help
from the well. It is kicking.

Noon TP 0# FL 1500' from surface. Ran swab to 4000'. Rec. gas, oil, mud. 30' flare.

12:30 PM FL 1500' from surface. Ran swab to 4500'. Well kicked off. 150' flare. Gas

1:00 PM FL 800' from surface. Ran swab to 5042' - seating nipple. Flare 120'.
Unloading gas & oil.

1:30 PM FL 1000' from surface. Ran swab to seating nipple. Flare 150'. Gas, oil
and drilling mud.
Maintaining 20' flare on 1" choke

Will continue to swab until dark. Will call in another report at 5 PM.

FL 1500' from surface. Ran swab to seating nipple. Flare 120'. Unloading
oil, gas and mud.

2:00 PM

=

2:30 PM Same as 2:00 PM

3:00 PM Same as 2:00 PM

3:30 PM Could not get in.

4:00 PM Same as 2:00 PM

Do not believe we can get back in again tonight. Will SD overnight and commence
swabbing again in the morning at 8:00 AM.