			AN 3		- ·			C.r.
Form <b>9-331</b> (May 1963)	NITED STATES							
	DEPARTMENT OF THE INTERIOR Verse store (Contract Instructions on re-					5. LEASE DESIGNATION AND SERIAL NO.		
	GI	EOLOGICAL SU	JRVEY		OPY-	NM-1	4118	
SUNDRY NOTICES AND REPORTS ON WELLS						6. IF INDIAN, ALLORECEIVED NAME		
	its form for proposal	s to drill or to deer	en or plug back	to a different re	servoir			
	Use "APPLICAT	ION FOR PERMIT-	-" for such propo-	RFCF	FIVED	).		1 0
1.	<b>n</b> =7)					7. UNIT AC	BRENENE	1980
WELL GAS	X OTHER				1000			
2. NAME OF GPERATOR				JUL -	1980	8. FARM O	R LEASE DAM	C.D.
Yates Petroleum Corporation						Allison AKOKSIA, Dederal		
3. ADDRESS OF OPERATOR U.S. GEULUGIUAL SUNV							0.	
207 South 4	th Street	- Artesia	, NM 88	21 ARTERIA	NEW HEXC			
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface						Und. Boyd Morrow		
						SUBJEC, T., B., M., OB BLK, AND SUBVEY OR AREA		
	d 1900 11	D OL DECL	1011 13-1	95-24E J				
				11 8 1	2644 145-054		13-195	
14. PERMIT NO.		15. ELEVATIONS (Sho	w whether DF. BT		EULUGICAL			
			3613'	<b>/1</b> 011	esia, new n	1		
	······			GR		Edc	iy	<u> </u>
16.	Check App	ropriate Box To	Indicate Natu	re of Notice,	Report, or C	Other Data		
NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:				
TEST WATER SHUT	POFF	LL OR ALTER CASING		WATER SHUT-	OFF	7	REPAIRING W	ELL
FRACTURE TREAT	м	LTIPLE COMPLETE		FRACTURE THE	EATMENT X		ALTERING CA	SING
SHOOT OR ACIDIZE	AB	ANDON*		SHOOTING OR	ACIDIZING X	_	ABANDONMEN	r•
REPAIR WELL	Сн	ANGE PLANS		(Other)				
(Other)	·			(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)				
17. DESCRIBE PROPOSED proposed work, nent to this work	If well is directiona	TIONS (Clearly state lly drilled, give sub	all pertinent de surface locations	tails, and give p and measured a	ertinent dates, nd true vertica	including es al depths for	timated date all markers	of starting any and zones per l-

AISF

TD 9320'; WLPBTD 9290' - WIH w/Tubing Conveyed gun and Baker Lok-Set packer on 2-7/8" tubing, set packer at 8916'. Perforated 8950-8960! w/40 .50" holes (4spf). No GTS. Ran swab and swabbed dry. Had trace of gas TSTM. Pulled guns. WIH w/Baker Lok-Set packer on 2-7/8" tubing, set packer at 8920'. Acidized perforations w/2500 gallons 71% MS acid and nitrogen w/ ball sealers. Sand Frac'd w/16000g treated fluid, 8000g CO-2 and 50000# sand. Swabbed dry in 3 runs. Well stabilized at 90# on 1/8" choke. Killed well, pulled packer out of hole at 8920'. RIH w/RBP set at 8930'. WIH w/Casing gun on wireline and perforated 8804-8904 w/14 .50" holes as follows: 8804, 05, 06, 17,  $17\frac{1}{2}$ , 18,  $18\frac{1}{2}$ , 19, 8898, 99, 8901, 02, 03 & 04. POOH. RIH w/ Guiberson Uni VI packer, set packer at 8775'. Swabbed dry. Acidized perforations w/2500 gallons  $7\frac{1}{2}\%$  acid and nitorgen. Flowing 30# on 1/2" choke. Sand Frac'd perforations w/ 16000g gelled 3% acid and 8000 gallons CO-2 and 19000# sand.w/ball sealers. Flowing back load. Pulled RBP at 8930' and opened all perforations from 8804-8960'. Well cleaned up and flowed 90# on 1/2" choke.

18. I hereby certify that the foregoing is true and correct SIGNED	Geol. Secty.	DATE 7-7-80
(This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY :	ACTING DISTRICT ENGINEER	DATE JUL 9 1980

\*See Instructions on Reverse Side