

N.M.O.C.D. COPY

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-029392(B)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Hinkle Federal "B"

9. WELL NO.
12

10. FIELD AND POOL, OR WILDCAT
Shugart

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
35 - 18S - 31E

12. COUNTY OR PARISH
Eddy

13. STATE
New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to the surface. For such proposals, use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

JUN 4 1980

2. NAME OF OPERATOR
WESTALL - MASK

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

3. ADDRESS OF OPERATOR
P.O. Drawer 1477, Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

330' FSL and 990' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3630.5 Gr.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

PULL OR ALTER CASING ☐

WATER SHUT-OFF ☐

REPAIRING WELL ☐

FRACTURE TREAT ☐

MULTIPLE COMPLETE ☐

FRACTURE TREATMENT ☐

ALTERING CASING ☐

SHOOT OR ACIDIZE ☐

ABANDON* ☐

SHOOTING OR ACIDIZING ☐

ABANDONMENT* ☐

REPAIR WELL ☐

CHANGE PLANS ☐

(Other) Run Casing

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

On 5/24/80 the following work was performed on the above well:

3 Hr. Circ. to log. 7 3/4 Logging

On 5/25/80 the following work was performed on the above well:

Lay down drill pipe and drill collars.

Set slips in 4 1/2" casing, cut off pipe and jet pits.

Ran 95 jts. 4,208' 9 1/2" 4 1/2" casing; Cement at 4200 w/475 sx. 50/50 pas,

2% calcium chloride 3/10 of 1% CFR2 8# salt 1/4# flo seal.

Plugged down. Rig released.

18. I hereby certify that the foregoing is true and correct

Personal Representative for
the Estate of Jack Mask

DATE 6/2/80

SIGNED Richard E. Barton

TITLE

(This space for Federal or State office use)

APPROVED BY (Sgd.) GEORGE H. STEWART TITLE
CONDITIONS OF APPROVAL, IF ANY:

SENIOR DISTRICT ENGINEER

DATE JUN 05 1980

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.