		C.U.U.	UUPY		C.5F
Form 9-331 (May 1963)	L TED ST DEPARTMENT OF T GEOLOGICAL	HE INTERIOF	SUBMIT IN TR (Other Instruction verse side)		Form approved. Budget Burgau No. 42-RE424. 5. LEASE REGENCED ND SERIAL NO. NM-0439491.
(Do not use th	NDRY NOTICES AND his form for proposals to drill or to Use "APPLICATION FOR PERM			5	$\frac{\mathbf{G}_{\text{IP}}}{\mathbf{G}_{\text{IP}}} = \frac{\mathbf{G}_{\text{IP}}}{\mathbf{G}_{\text{IP}}} = \frac{\mathbf{G}_{\text{IP}}}{\mathbf{G}_{\text{IP}}$
1. OIL CAS WELL WELL	OTHER				ARTESIA, OFFICE ?
2. NAME OF OPERATOR			MAY - 5 1980		8. FARM OR LEASE NAME
	oleum Corporation		GEULUGICAL SUR		Pederal "CW"-B
3. ADDRESS OF OPERATOR 207 South 4th Street-Artesia, NM 882ARTESIA, NEW MEXICO					8
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*					10. FIELD AND POOL, OR WILDCAT
See also space 17 below.)					enasco Draw SA-Yeso
At surface $330'$ FSL & $330'$ FEL of Section 1-19S-24E					11. SEC., T., R., M., OR BLK. AND (ASSOC) SURVEY OR AREA
					Sec. 1-195-24E Unit P NMPM
14. PERMIT NO.	1 15 57 574 710 79	(Show whether DF, RT,	CR etc.)		12. COUNTY OF PARISH 13. STATE
14. PERMIT NO.		39' GR			Eddy NM
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data					
	NOTICE OF INTENTION TO:			SUBSEQUEN	NT REPORT OF:
TEST WATER SHU	T-OFF PULL OR ALTER CA	SING	WATER SHUT-OFF	X	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLE	TE	FRACTURE TREATME	NT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	·	SHOOTING OR ACIDI		4 <sup>1</sup> / <sub>2</sub> " CSQ.
REPAIR WELL	CHANGE PLANS		(Other) Spud		<u>4%</u> CSG. X f multiple completion on Well
(Other)	-		Completion of	r Recomplet:	ion Report and Log form.)
17. DESCRIBE PROPOSED proposed work. nent to this work	If well is directionally drilled, give	state all pertinent de subsurface location:	etails, and give perting and measured and tr	ue vertical	ncluding estimated date of starting any depths for all markers and zones perti-
Spudded a	15" hole at 1:30 P	м 4-17-80.			
			T&C J-55 (3	91') c	of casing set at
TD 390' - Ran 10 jts of 10-3/4" 40# ST&C J-55 (391') of casing set at 390'. 1-Texas pattern guide shoe at 390' and insert float at 350'. Cemented					
w/350 sacks Class C 4% CaCl. PD 12:45 AM 4-18-80. Cement circulated 35					
sacks to surface. WOC 12 hours , backed off, reduced hole to 91/2", drilled					
plug, tested to 600# OK and resumed drilling.					
TD 975' - Ran 37 joints of 7" 20# J-55 ST&C (978') of casing set at 975'.					
1-guide shoe at 975' and insert float at 954'. Cemented w/250 sacks of					
Class C Neat, 450 sacks 65-35 Poz, 8#/sx Kolite, 1/4#/sx celloflakes,					
					D 6:00 PM 4-19-80.
Cement cir	culated 50 sacks c	f cement t	o the surfa	ce. V	NOC 18 hours NU &
tested to	1000#, reduced hol	e to 64",	drilled plu	ig and	tested to 600# OK.
Pogumod dr	illing	. –			
<u>TD 3100';</u>	<u>PBTD 3095'</u> - Ran 7	'l joints c	t 4½" 9.5#	K-55	(3097.) of casing
	5'. 1-guide shoe a				
3/10% CFR-	2, 2/10% Halad-9.	PD 1:00 PM	4-26-80. C	ircula	ated 35 sacks of
cement to	the surface.				
				·	
18. I hereby certify	hat the foregoing is true and correct	et C			5-3-80
SIGNED		conTITLE	eol. Secty.		DATE
(This specific lar	Edral or State office use)				
APPROVED BY		ALING DI	STRICT ENGIN		DATE 0.7 133

\*See Instructions on Reverse Side

z